

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

HSIAO Tony

Not Authorized
14/09/22
2/sf 3500/
3 days.

VEHICLE No: SLB 8717K

1PC	FRONT BUMPER	needed / To-1	\$863.00	✓
1PC	FRONT BUMPER CENTRE GARNISH [BLACK]	11	\$517.00	✓
1PC	FRONT BUMPER CENTRE CHROME GARNISH	11	\$321.00	✓
1PC	FRONT BUMPER N/S CHROME MOULDING LOWER	scr	\$112.00	✓
1PC	FRONT BUMPER N/S CHROME MOULDING TOP	scr	\$220.00	✓
1PC	FRONT BUMPER FOG LAMP N/S	one	\$348.00	✓
1PC	FRONT BUMPER FOG LAMP COVER N/S	scr	\$68.00	✓
1PC	FRONT BUMPER BEAM	11	\$305.00	✓
1PC	FRONT BUMPER SIDE RETAINER N/S	3sf	\$45.00	✓
1SET	FRONT BUMPER CLIPS	11	\$50.00	✓
1PC	HEADLAMP N/S	holder one	\$2,548.00	✓
1PC	HEADLAMP NOZZLE N/S	one	\$299.00	✓
1PC	HEADLAMP NOZZLE COVER N/S	cut	\$53.00	✓
1PC	FRONT GRILLE ASSY	11	\$550.00	✓
1PC	FRONT SUPPORT PANEL	R	\$648.00	✓
			\$6,947.00	
			LESS 10%	\$6,252.30

TO CHECK WIRING
TO DISMANTLE & REFIX FRONT PDC SENSOR
TO RESET & DIAGNOSTIC SYSTEM
TO SPRAY RUST PROOFING
TO REFILL AIR CON GAS
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

	\$50.00	20
11	\$80.00	✓
11	\$120.00	✓
11	\$60.00	✓
11	\$120.00	✓
	\$600.00	450
	\$800.00	400
TOTAL	\$8,082.30	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2-3913
102
3521.7
870
4391.7
202
3513