

# ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road  
#08-1339 Singapore 470130

Tel: 9450 7920

\* zoomautowerks@gmail.com



*Not Authorized*

29 September 2022

*dlr*  
*14/09/22*  
*1/5 \$3600*  
*5 days*

REG NO. : GBK 5284 H  
MAKE/MODEL : TOYOTA HIACE

**ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE**

**AMT(S\$)**

QTY	DESCRIPTION		AMT(S\$)
	<b>LIST ITEMS</b>		
1	Front corner panel -RH	<i>R</i>	\$ 376.50 X
1	Front headlamp -RH	<i>1 1</i>	\$ 1,700.20 X
1	Front bumper	<i>1 1</i>	\$ 862.16 X
1	Front bumper side bracket	<i>1 1</i>	\$ 89.30 X
1	Front door -RH	<i>R</i>	\$ 1,670.00 X
1	Front door checker		\$ 35.80 X
1	Front door glass outer moulding	<i>1 1</i>	\$ 133.95 X
2	Front door hinges	<i>1 1</i>	\$ 155.96 X
1	Front door inner board	<i>1 1</i>	\$ 897.50 X
1	Front door lock	<i>1 1</i>	\$ 272.50 X
1	Front door outer handle	<i>scr</i>	\$ 163.50 ✓
1	Front door regulator	<i>1 1</i>	\$ 211.36 X
1	Front door regulator motor	<i>1 1</i>	\$ 489.55 X
1	Front door rubber	<i>1 1</i>	\$ 190.05 X
1	Front door side mirror	<i>CR</i>	\$ 450.60 ✓
1	Front door outer pillar -RH	<i>R</i>	\$ 711.50 X
1	Front rear pillar -RH	<i>scr / surf</i>	\$ <i>681.10</i> <del>822.59</del> ✓
1	Sliding door -RH	<i>scr / surf</i>	\$ <i>1545.10</i> <del>1,611.00</del> ✓
1	Sliding door lock	<i>1 1</i>	\$ 282.50 X
1	Sliding door lock striker	<i>1 1</i>	\$ 68.50 X
1	Sliding door rubber	<i>1 1</i>	\$ 287.00 X
1	Sliding door inner board	<i>1 1</i>	\$ 444.00 X
1	Sliding door centre roller	<i>1 1</i>	\$ 223.50 X
1	Sliding door centre track	<i>1 1</i>	\$ 483.12 X
1	Sliding door outer handle	<i>scr</i>	\$ 198.10 ✓
1	Sliding door lower roller	<i>1 1</i>	\$ 173.50 X
1	Rear taillamp -RH	<i>scr</i>	\$ <i>361.10</i> <del>385.50</del> ✓
1	Rear side body panel -RH	<i>R</i>	\$ 1,765.50 X
			\$ 15,155.24
			Less 25% \$ 3,788.81
			\$ 11,366.43

**SPECIAL NETT ITEMS**

1	Front bumper clip (1 set)	AM	\$	60.00	50
1	Front door lettering sticker	AM	\$	45.00	✓
1	Rear side panel sticker	11	\$	250.00	X
			\$	<u>355.00</u>	

**S/N LABOUR CHARGES**

1	To check wiring and reset headlamps focusing.		\$	80.00	
2	To remove, replaced damaged lamps and check up rear wiring.		\$	80.00	30
3	To remove and refit inner garnishes.	~	\$	150.00	X
4	To remove and refit rear reverse sensor.	~	\$	120.00	X
5	To remove, refit door fittings and replace damaged parts, transfer all fittings to new door.		\$	400.00	60
6	To apply undercoating.		\$	200.00	80
7	Panel beating.		\$	1,800.00	1100
8	To re-spray painting on the affected areas.		\$	1,600.00	600
			\$	<u>4,430.00</u>	

**GRAND TOTAL :**

**\$ 16,151.43**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

12-3399.50  
252  
 2849.62  
 1870  
95  
 4514.62  
207  
 3611