

CHOO MOTOR SPRAY PAINTER
1 KAKI BUKIT AVE 6 #01-39 AUTOBAY
SINGAPORE 417883

HS140 Tony

NO + Authorised
Signature

14/09/22

2/542800/
4 days.

VEHICLE No: GBC 9415M

1PC	TAILGATE	R	\$2,159.10	X
1PC	TAILGATE REAR LOGO	new	\$68.10	/
1PC	TAILGATE 'HIACE' EMBLEM	new	\$80.50	X
1PC	TAILGATE '70Km/h' STICKER	new	\$15.00	10s/W
1PC	REAR BUMPER	R	\$681.00	X
1PC	REAR BUMPER SIDE RETAINER O/S	new	\$105.00	X
1SET	REAR BUMPER CLIPS	new	\$50.00	X
1PC	TAILLAMP O/S	one	368.10	\$488.50
1PC	TAILLAMP LOWER GARNISH O/S	new	\$180.20	X
1PC	TAILLAMP LOWER GARNISH BRACKET O/S	new	\$100.30	X
1PC	TAILLAMP HOUSING PANEL O/S	new/can	445.10	\$482.50
1PC	REAR END PANEL OUTER	R	\$650.10	X
1PC	REAR FENDER O/S	new/can	(252) 1645.20	\$2,010.50
				\$7,070.80

TO CHECK WIRING
TO DISMANTLE & REFIX REAR REVERSE SENSOR
TO DISMANTLE & REFIX REAR WINDSCREEN
TO TRANSFER TAILGATE MECHANISM
TO SPRAY RUST PROOFING
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

	\$50.00	20
new	\$80.00	X
new	\$150.00	X
new	\$100.00	X
	\$100.00	50
	\$1,200.00	900
	\$1,100.00	650
TOTAL	\$9,850.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2-2526.10
252
1894.87
1620
3514.87
202
2811