



Main Office : No. 22, Jalan Kilang, Singapore 159410
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/116, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088364-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading
Dealing in New/Used Cars, Hire Purchase & Insurance



INSURER:

Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	0	Date of Loss:	01/09/2022
Vehicle Reg. No.:	SMH7237S	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	WANG DEHAI		
Make/Model:	TOYOTA ALPHARD, 2.5 SC CVT (A)	Vehicle Reg. Date:	30/01/2019
Vehicle Colour:	WHITE	Chassis No:	AGH300214515
Engine No:	2ARJ214361		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	12		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	17,869.55
Miscellaneous Items	0.00
Labour	3,480.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	21,349.55
+ GST 7.00% (\$\$)	1,494.47
Nett Amount (\$\$)	22,844.02

This claim is handled by: BRIAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

DETAILS

Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Sep 2022)
 M1-MPV TOYOTA ALPHARD 2.5 SC CVT (A) (Catalogue:Merimen Singapore 1.0)
 Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SMH7237S)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET / <i>DN</i>	0.00	0.00	*350.00 F ✓
2	2		*BONNET HINGE LH/RH / <i>BT</i>	0.00	0.00	*70.00 F ✓
3	1		*BONNET INSULATOR / <i>CRU</i>	0.00	0.00	*100.00 F ✓
4	10		*BONNET INSULATOR CLIPS / <i>MC</i>	0.00	0.00	*20.00 F ✓
5	1		*BONNET STANDS / <i>MS</i>	0.00	0.00	*35.00 F ✓
6	1		*BONNET LOCK / <i>BT</i>	0.00	0.00	*90.00 F ✓
7	1		*BONNET CHROME GARNISH / <i>MS</i>	0.00	0.00	*170.00 F ✓
8	2		*HEADLAMP LH/RH / <i>OR</i>	0.00	0.00	*5,460.00 F ✓
9	1		*HEADLAMP ECU LH / <i>✓ MIS</i>	0.00	0.00	*400.00 F ✓
10	1		*FRONT BUMPER / <i>OR</i>	0.00	0.00	*950.00 F ✓
11	2		*FRONT BUMPER SENSOR / <i>MS</i>	0.00	0.00	*360.00 F ✓
12	1		*FRONT BUMPER SENSOR WIRE / <i>MS</i>	0.00	0.00	*250.00 F ✓
13	2		*BUMPER RETAINER LH/RH / <i>OR</i>	0.00	0.00	*100.00 F ✓
14	20		*BUMPER CLIPS / <i>MC</i>	0.00	0.00	*40.00 F ✓
15	10		*BUMPER CLIPS / <i>NN</i>	0.00	0.00	*20.00 F ✓
16	1		*RADIATOR GRILLE, TOP COVER / <i>OR</i>	0.00	0.00	*150.00 F ✓
17	10		*RADIATOR GRILLE, TOP COVER CLIPS / <i>MC</i>	0.00	0.00	*20.00 F ✓
18	1		*FRONT FENDER LH/RH / <i>DN</i>	0.00	0.00	*840.00 F ✓
19	1		*FRONT FENDER INNER LINER RH / <i>TN</i>	0.00	0.00	*170.00 F ✓
20	20		*FRONT FENDER INNER LINER CLIPS / <i>MC</i>	0.00	0.00	*40.00 F ✓
21	1		*FRONT FENDER SIDE, PIN HOLD CLIPS / <i>MC</i>	0.00	0.00	*5.50 F ✓
22	1		*RADIATOR GRILLE / <i>OR</i>	0.00	0.00	*1,020.00 F ✓
23	1		*ALPHARD LOGO / <i>MC</i>	0.00	0.00	*700.00 F ✓
24	1		*RADAR / <i>✓ BR</i>	0.00	0.00	*1,200.00 F ✓
25	1		*RADAR WIRE / <i>OR</i>	0.00	0.00	*250.00 F ✓
26	1		*NUMBER PLATE BACKING PLATE / <i>CRU</i> X <i>NN</i>	0.00	0.00	*85.00 F ✓
27	1		*TOWING COVER / <i>MS</i>	0.00	0.00	*40.00 F ✓
28	1		*FRONT BUMPER FOG LAMP BRKT LH/RH (RH) / <i>OR</i>	0.00	0.00	*90.00 F 45 ✓
29	1		*FRONT BUMPER FOG LAMP LH/RH (RH) / <i>CRU</i>	0.00	0.00	*300.00 F 150 ✓
30	2		*FRONT BUMPER FOG LAMP OUTER CHROME LH/RH / <i>CRU</i>	0.00	0.00	*340.00 F ✓
31	1		*FRONT BUMPER FOG LAMP GARNISH LH/RH (RH) / <i>CRU</i>	0.00	0.00	*440.00 F 220 ✓
32	1		*FRONT BUMPER LOWER AIR GRILLE / <i>CRU</i>	0.00	0.00	*130.00 F ✓
33	1		*FRONT BUMPER UNDERNEATH COVER / <i>CRU</i>	0.00	0.00	*150.00 F ✓
34	1		*BUMPER SPONGE / <i>MS</i>	0.00	0.00	*55.00 F ✓
35	1		*BUMPER REINFORCEMENT / <i>MI</i>	0.00	0.00	*210.00 F ✓
36	1		*ROOF MOULDING LH/RH (RH) / <i>CRU</i>	0.00	0.00	*400.00 F 200 ✓
37	1		*HORN / <i>OR</i>	0.00	0.00	*85.00 F ✓
38	1		*WASHER TANK / <i>CRU</i>	0.00	0.00	*110.00 F ✓
39	1		*SUPPORT - TOP PANEL / <i>BT</i>	0.00	0.00	*300.00 F ✓
40	1		*SUPPORT - SIDE PANEL (RH) / <i>BT</i>	0.00	0.00	*470.00 F 235 ✓
41	1		*SUPPORT - LOWER PANEL (CHECK) / <i>NN</i>	0.00	0.00	*75.00 F ✓
42	1		*BRACE PANEL / <i>BT</i>	0.00	0.00	-
43	1		*A/C CONDENSER (CHECK) / <i>BT</i> (no price)	0.00	0.00	-
44	1		*RADIATOR (CHECK) / <i>NN</i>	0.00	0.00	-
45	1		*COOLANT / <i>MC</i>	0	0.00 30 ✓	*80.00 FS
46	1		*A/C GAS / <i>MC</i>	0	0.00	*50.00 FS ✓
47	1		*NUMBER PLATE / <i>OR</i>	0	0.00	*40.00 FS ✓

F=Franchise part, S=SpcNett.

Sub Total (\$\$) 16,260.50
 + Margin on L,N Items 10.00% (\$\$) 1,609.05
 Total Parts (\$\$) 17,869.55

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items
no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO CUT/ WELD/ KNOCKING FRONT SUPPORT PANEL, REPLACE LH/RH SIDE PANEL, FRONT BUMPER, BONNET & REALIGN ALL THE CONNECTION	New 1200	1,350.00
2	TO SPRAY PAINT ON BONNET, FRONT BUMPER, FENDER LH/RH, RH FRONT DOOR	New	1,100.00 ✓
3	TO REMOVE/ REFIT A/C CONDENSE & RADIATOR	New 780	150.00
4	TO ADJUST FOCUS HEADLAMP & CALIBRATION 1000/12	New 300	250.00
5	TO PROGRAM RADAR & CALIBRATION ADAS	New 30	450.00
6	TO APPLY ANTI RUST PROOFING ON AFFECTED AREAS	New 30	60.00
7	TO CHECK & RECTIFY WIRING FAULT. TO CONDUCT DIAGNOSTIC CHECK & FUNCTIONAL CHECK	New 100	120.00
Gross Labour Cost (\$\$)			3,480.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve (LKK)

14/7/22, 12:30 pm

CD-M AL

Excess-?

P/P

by BEL
9 d/s

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: