

**Trans-cab Auto Services Pte Ltd**

AAD2209-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD332B**

Vehicle No.:	<b>SHD332B</b>
Chassis No.:	VF1ABL15AUC282681
UEN No:	200303878K
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	13/09/2022
Third Party Insurer :	<b>SLW6583G/ Allianz</b>
Date of Registration :	04/03/2016

<b>PART</b>		<b>LIST</b>
1 FENDER PANEL FRT RH	\$	437.10
1 WHEELARCH FRT RH	\$	191.40
1 MOULDING ASSY, BODY ROCKER PANEL, RH	\$	594.80
1 DOOR PANEL FRT RH	\$	2,844.66
1 DOOR WEATHERSTRIP FRT RH	\$	410.27
1 DOOR HANDLE OUTER FRT RH	\$	477.76
1 DOOR HANDLE MODULE FRT RH	\$	133.60
1 DOOR REGULATOR FRT RH	\$	505.19
1 DOOR REGULATOR MOTOR FRT RH	\$	796.46
1 DOOR HINGE UPPER FRT RH	\$	261.28
1 DOOR HINGE LOWER FRT RH	\$	300.55
1 DOOR PANEL REAR RH	\$	2,844.66
1 DOOR WEATHERSTRIP REAR RH	\$	311.60
1 DOOR HANDLE MODULE REAR RH	\$	133.40
1 DOOR HANDLE OUTER REAR RH	\$	42.10
1 DOOR REGULATOR REAR RH	\$	450.60
1 DOOR REGULATOR MOTOR REAR RH	\$	758.10
1 DOOR HINGE UPPER REAR RH	\$	241.60
1 DOOR HINGE LOWER REAR RH	\$	169.90
	<b>\$</b>	<b>11,905.03</b>
	<b>10% \$</b>	<b>1,190.50</b>
	<b>\$</b>	<b>10,714.52</b>

**Special Nett**

1 DOOR TRIM CLIP	\$	70.00
1 DOOR SEAL CLIP	\$	65.00

**Trans-cab Auto Services Pte Ltd****AAD2209-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD332B**

1	DOOR MOULDING CLIP	\$	70.00
1	DOOR STICKER TRANSCAB	\$	100.00
1	DOOR STICKER 65553333	\$	100.00
1	DOOR STICKER CLASSIC	\$	100.00
2	WINDSCREEN SEALANT	\$	150.00
1	WINDSCREEN MOULDING	\$	200.00
1	WINDSCREEN INNER SPONGE SEAL	\$	130.00
<b>TOTAL</b>		<b>\$</b>	<b>985.00</b>
<b>TOTAL PARTS</b>		<b>\$</b>	<b>11,699.52</b>

**LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	300.00
Putty And Spray Painting Of The Affected Portion.	\$	3,000.00
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00
To Rust-Proofing Of The Affected Areas.	\$	170.00
To reinstall rear bumper parking sensor.	\$	170.00
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00
To repair and realign rear exhaust pipe.	\$	170.00
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00

**Trans-cab Auto Services Pte Ltd**

**AAD2209-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD332B**

To check steering geometry and computer wheel alignment	\$	220.00
---	----	--------

To Check Electrical Lighting Concerned.	\$	170.00
---	----	--------

<b>TOTAL</b>	<b>\$</b>	<b>7,880.00</b>
--------------	-----------	-----------------

<b>Over All Total</b>	<b>\$</b>	<b>30,294.05</b>
-----------------------	-----------	------------------

**(LUMP SUM)**

**Repair Days**

**20 DAYS**

> Back to OneMotoring



Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 13 Sep 2022 / 14:42:52

Receipt Date/Time : 13 Sep 2022 / 14:42:52

### Tax Invoice/Receipt

Receipt No. : ITNET-00000-220913-002397

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - FBS3405Y As at 12 Sep 2022/13:35:00 Insurance Co: INCOME INSURANCE LIMITED				
1	Insurance Enquiry - FBS3405Y Enquiry Fee 20220913144006370598	7.00	0.49	7.49
<b>Sub-Total</b>		7.00	0.49	7.49
Result of Insurance Enquiry - SLW6583G As at 13 Sep 2022/09:45:00 Insurance Co: ALLIANZ INSURANCE SINGAPORE PTE. LTD.				
2	Insurance Enquiry - SLW6583G Enquiry Fee 20220913144006554239	7.00	0.49	7.49
<b>Sub-Total</b>		7.00	0.49	7.49
Result of Insurance Enquiry - YN5100S As at 12 Sep 2022/17:58:00 Insurance Co: INCOME INSURANCE LIMITED				
3	Insurance Enquiry - YN5100S Enquiry Fee 20220913144006694951	7.00	0.49	7.49
<b>Sub-Total</b>		7.00	0.49	7.49
Result of Insurance Enquiry - SLL6856C As at 13 Sep 2022/09:45:00 Insurance Co: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD				
4	Insurance Enquiry - SLL6856C Enquiry Fee 20220913144006791761	7.00	0.49	7.49
<b>Sub-Total</b>		7.00	0.49	7.49
<b>Total Before Rounding</b>		28.00	1.96	29.96
<b>Rounding Difference</b>				0.01
<b>Total Amount Payable</b>				29.95
Paid By				
	554827XXXXXX5467	eNETS Credit Card		29.95
<b>Total</b>				29.95
Cash Change				0.00
Tendered Amount				29.95
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!