

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD332B

AAD2209-

Vehicle No.:	SHD332B
Chassis No.:	VF1ABL15AUC282681
UEN No.:	200303878K
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	13/09/2022
Third Party Insurer :	TOTAL SLW6583G/ Allianz
Date of Registration :	TOTAL PARTS 04/03/2016

PART	LIST
1 FENDER PANEL FRT RH <i>bt/</i>	\$ 437.10
1 WHEELARCH FRT RH <i>Xm</i>	\$ 191.40 <i>X</i>
1 MOULDING ASSY, BODY ROCKER PANEL, RH <i>Xm</i>	\$ 594.80 <i>X</i>
1 DOOR PANEL FRT RH <i>bt/</i>	\$ 2,844.66
1 DOOR WEATHERSTRIP FRT RH <i>m/</i>	\$ 410.27
1 DOOR HANDLE OUTER FRT RH <i>repair</i>	\$ 477.76 <i>XR</i>
1 DOOR HANDLE MODULE FRT RH <i>Xm</i>	\$ 133.60 <i>X</i>
1 DOOR REGULATOR FRT RH <i>Xm</i>	\$ 505.19 <i>X</i>
1 DOOR REGULATOR MOTOR FRT RH <i>Xm</i>	\$ 796.46 <i>X</i>
1 DOOR HINGE UPPER FRT RH <i>Xm</i>	\$ 261.28 <i>X</i>
1 DOOR HINGE LOWER FRT RH <i>Xm</i>	\$ 300.55 <i>X</i>
1 DOOR PANEL REAR RH <i>bt/</i>	\$ 2,844.66
1 DOOR WEATHERSTRIP REAR RH <i>m/</i>	\$ 311.60
1 DOOR HANDLE MODULE REAR RH <i>Xm</i>	\$ 133.40 <i>X</i>
1 DOOR HANDLE OUTER REAR RH <i>Xm</i>	\$ 42.10 <i>X</i>
1 DOOR REGULATOR REAR RH <i>Xm</i>	\$ 450.60 <i>X</i>
1 DOOR REGULATOR MOTOR REAR RH <i>Xm</i>	\$ 758.10 <i>X</i>
1 DOOR HINGE UPPER REAR RH <i>Xm</i>	\$ 241.60 <i>X</i>
1 DOOR HINGE LOWER REAR RH <i>Xm</i>	\$ 169.90 <i>X</i>
<i>RH</i> 1 Side view mirror assy <i>cm/</i> 1483.40	\$ 11,905.03 <i>8331.69</i>
10%	\$ 1,190.50 <i>10%</i>
	\$ 10,714.52 <i>7498.52</i>

Special Nett

1 DOOR TRIM CLIP <i>m/</i>	\$ 70.00 <i>30</i>
1 DOOR SEAL CLIP <i>X</i>	\$ 65.00 <i>X</i>

Trans-cab Auto Services Pte Ltd

AAD2209-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD332B

1	DOOR MOULDING CLIP <i>nn</i>	\$	70.00 30
1	DOOR STICKER TRANSCAB <i>nn</i>	\$	100.00 80
1	DOOR STICKER 65553333 <i>nn</i>	\$	100.00 50
1	DOOR STICKER CLASSIC <i>nn</i>	\$	100.00 50
2	WINDSCREEN SEALANT <i>X nn</i>	\$	150.00 X
1	WINDSCREEN MOULDING <i>X nn</i>	\$	200.00 X
1	WINDSCREEN INNER SPONGE SEAL <i>X nn</i>	\$	130.00 X
	TOTAL	\$	985.00
	TOTAL PARTS	\$	11,699.52 <i>240</i>

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	(LUMP SUM)	\$	300.00 <i>X nn</i>
Putty And Spray Painting Of The Affected Portion.	Repair Days	\$	3,000.00 <i>600</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same		\$	3,000.00 <i>600</i>
To Rust-Proofing Of The Affected Areas.		\$	170.00 40
To reinstall rear bumper parking sensor.		\$	170.00 <i>X nn</i>
To transfer of bootlid fittings, attachments and perform water seepage test.		\$	170.00 <i>X nn</i>
To repair and realign rear exhaust pipe.		\$	170.00 <i>X nn</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.		\$	170.00 <i>X nn</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.		\$	170.00 <i>X nn</i>
To transfer of rear windscreen fittings and conduct water seepage test.		\$	170.00 <i>X nn</i>

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD332B

AAD2209-

To check steering geometry and computer wheel alignment

\$ 220.00 *Xan*

To Check Electrical Lighting Concerned.

\$ ~~170.00~~ *30*

TOTAL \$ 7,880.00

Over All Total \$ 30,294.05

1270

(LUMP SUM)

Repair Days

20 DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

7498.52

240.00

1270.00

9008.52

20%

7206.81

45 - \$7,200

Rasul
Hp 90010068
6 days

45

15/09/22 @ 1435

Resy after repair

email: rasul@lkk auto.com

Trans-cab Auto Services Pte Ltd

AAD2209-078

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD332B

Vehicle No.:	SHD332B
Chassis No.:	VF1ABL15AUC282681
UEN No.:	200303878K
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	13/09/2022
Third Party Insurer :	SLW6583G/ALLIANZ
Date of Registration :	04/03/2016

SUPPLEMENTARY

PART

LIST

1 DOOR MIRROR ASSY RH <i>CA</i>	\$	1,483.40
	\$	1,483.40
	10% \$	148.34
	\$	<u>1,335.06</u>

Yes
 TRANS-CAB SERVICES PTE LTD
 20000078K
 Singapore
 (Mobile) +65-92876666
 (Fax) +65-62571330