

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009040/TVY3M4**Date:** 14/12/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00263252101		
Claimant Vehicle No :	SKT4208G	Insured Vehicle No :	SMW4511R		
Date of Loss:	11/09/2022	Nature of Claim:	TP	Claim No:	SNM22D206527/C02/KAHLEONG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT4208G		Engine No:	3ZZ4813444
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)		Chassis No:	MR053ZEE106124180
Reg. Date:	22/12/2008 (Man. Year: 2008)		Odometer:	308815 km
Colour:	Beige			
Engine Capacity:	1598 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	25,633.78	3,204.66	22,429.12	87.50	
Miscellaneous Items	0.00	0.00	0.00		
Labour	6,800.00	1,270.00	5,530.00	81.32	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	32,433.78	4,474.66	27,959.12	86.20	
Approved Total (Overridden) (S\$)		3,100.00			
	(S\$)	32,433.78	3,100.00	29,333.78	90.44
	+ GST 7.00/7.00% (S\$)	2,270.36	217.00	2,053.36	90.44
	Nett Amount (S\$)	34,704.14	3,317.00	31,387.14	90.44

INSPECTION

Date of Assignment:	14/09/2022		
Date Inspected:	15/09/2022	Inspected At:	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Dec 2022)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKT4208G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	582.89 FL	*561.85 FL
2	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	52.50 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER LH	Not Necessary	52.50 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP LH	Not Necessary	183.60 FL	*- FL
5	1		*FRONT BUMPER FOG LAMP GARNISH LH	Not Necessary	91.20 FL	*- FL
6	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	395.20 FL	*- FL
7	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	198.50 FL	*- FL
8	1		*FRONT HEADLAMP ASSEMBLY RH	Not Necessary	528.60 FL	*- FL
9	1		*FRONT HEADLAMP ASSEMBLY LH	Not Necessary	528.60 FL	*- FL
10	1		*FRONT GRILLE	Not Necessary	316.60 FL	*- FL
11	1		*FRONT GRILLE EMBLEM	Not Necessary	65.00 FL	*- FL
12	1		*FRONT SUPPORT PANEL	Not Necessary	591.60 FL	*- FL
13	1		*FRONT BONNET	Not Necessary	845.10 FL	*- FL
14	1		*FRONT BONNET HINGE RH	Not Necessary	62.00 FL	*- FL
15	1		*FRONT BONNET HINGE LH	Not Necessary	62.00 FL	*- FL
16	1		*FRONT FENDER LH	Bent	498.10 FL	*374.10 FL
17	1		*FRONT FENDER EMBLEM LH	Necessary	55.90 FL	*55.90 FL
18	1		*FRONT FENDER INNER COWLING LH	Not Necessary	145.60 FL	*- FL
19	1		*FRONT SHOCK ABSORBER LH	Not Necessary	430.40 FL	*- FL
20	1		*FRONT KNUCKLE ARM LH	Not Necessary	427.20 FL	*- FL
21	1		*FRONT KNUCKLE ARM BEARING LH	Not Necessary	203.90 FL	*- FL
22	1		*FRONT LOWER ARM LH	Not Necessary	381.60 FL	*- FL
23	1		*FRONT TIE ROD LH	Not Necessary	206.80 FL	*- FL
24	1		*STEERING RACK AND PINION	Not Necessary	1,970.40 FL	*- FL
25	1		*FRONT DRIVE SHAFT LH	Not Necessary	1,842.60 FL	*- FL
26	1		*ROCKER PANEL GARNISH LH	Deformed	765.10 FL	*765.10 FL
27	1		*FRONT DOOR LH	Bent	1,102.80 FL	*1,102.80 FL
28	1		*FRONT DOOR SIDE MIRROR LH	Distorted	599.80 FL	*599.80 FL
29	1		*FRONT DOOR UPPER HINGE LH	Not Necessary	80.30 FL	*- FL
30	1		*FRONT DOOR LOWER HINGE LH	Not Necessary	80.30 FL	*- FL
31	1		*FRONT DOOR CHECKER LH	Not Necessary	62.10 FL	*- FL
32	1		*FRONT DOOR INNER LOCK LH	Not Necessary	324.60 FL	*- FL
33	1		*FRONT DOOR INNER TRIM BOARD LH	Not Necessary	668.70 FL	*- FL
34	1		*FRONT DOOR WEATHERSTRIP LH	Not Necessary	164.40 FL	*- FL
35	1		*FRONT DOOR WINDOW GLASS REGULATOR LH	Not Necessary	263.20 FL	*- FL
36	1		*FRONT DOOR WINDOW GLASS REGULATOR MOTOR LH	Not Necessary	657.40 FL	*- FL
37	1		*FRONT DOOR WINDOW OUTER MOULDING LH	Not Necessary	142.60 FL	*- FL
38	1		*REAR FENDER LH	Not Necessary	982.40 FL	*- FL
39	1		*REAR FENDER INNER COWLING LH	Not Necessary	110.45 FL	*- FL
40	1		*REAR FENDER AIR VENT LH	Not Necessary	138.00 FL	*- FL
41	1		*REAR WINDSCREEN GLASS OUTER MOULDING	Not Necessary	123.30 FL	*- FL
42	1		*REAR DOOR LH	Not Necessary	1,212.70 FL	*- FL
43	1		*REAR DOOR INNER LOCK LH	Not Necessary	482.40 FL	*- FL
44	1		*REAR DOOR BLACK TAPE LH	Not Necessary	44.00 FL	*- FL
45	1		*REAR DOOR GLASS OUTER MOULDING LH	Not Necessary	113.10 FL	*- FL
46	1		*REAR DOOR OUTER HANDLE LH	Not Necessary	172.50 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR DOOR WEATHERSTRIP LH	Not Necessary	173.50 FL	*- FL
48	1		*REAR DOOR INNER TRIM BOARD LH	Not Necessary	796.70 FL	*- FL
49	1		*REAR DOOR POWER WINDOW REGULATOR LH	Not Necessary	214.30 FL	*- FL
50	1		*REAR DOOR POWER WINDOW MOTOR LH	Not Necessary	619.40 FL	*- FL
51	1		*REAR DOOR UPPER HINGE LH	Not Necessary	91.30 FL	*- FL
52	1		*REAR DOOR LOWER HINGE LH	Not Necessary	91.00 FL	*- FL
53	1		*REAR SHOCK ABSORBER LH	Not Necessary	220.30 FL	*- FL
54	1		*REAR WHEEL HUB BEARING LH	Not Necessary	365.90 FL	*- FL
55	1		*REAR AXLE	Not Necessary	3,444.50 FL	*- FL
56	1		*REAR BUMPER	Not Necessary	495.20 FL	*- FL
57	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	60.00 FL	*- FL
58	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	60.00 FL	*- FL
59	1		*REAR BUMPER REFLECTOR LH	Not Necessary	60.40 FL	*- FL
60	1		*REAR END PANEL	Not Necessary	670.00 FL	*- FL
61	1		*REAR END PANEL TOP GARNISH	Not Necessary	241.90 FL	*- FL
62	1		*REAR TAILLAMP ASSEMBLY LH	Not Necessary	494.00 FL	*- FL
63	1		*REAR BOOTLID	Not Necessary	793.20 FL	*- FL
64	1		*REAR BOOTLID TAILLAMP LH	Not Necessary	353.30 FL	*- FL
65	1		*REAR BOOTLID EMBLEM	Not Necessary	61.60 FL	*- FL
66	1		*REAR BOOTLID COROLLA EMBLEM	Not Necessary	48.30 FL	*- FL
67	1		*REAR BOOTLID ALTIS EMBLEM	Not Necessary	43.50 FL	*- FL
68	1		*REAR BOOTLID 1.6 EMBLEM	Not Necessary	38.70 FL	*- FL
69	1		*REAR BOOTLID LOCK	Not Necessary	399.50 FL	*- FL
70	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
71	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
72	1		*SET FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
73	1		*SET FRONT FENDER INNER COWLING CLIPS LH	Not Necessary	50.00 FS	*- FS
74	1		*SET FRONT DOOR INNER TRIM BOARD CLIPS LH	Not Necessary	50.00 FS	*- FS
75	1		*SET REAR DOOR INNER TRIM BOARD CLIPS LH	Not Necessary	50.00 FS	*- FS
76	1		*SET ROCKER PANEL GARNISH CLIPS LH	Necessary	50.00 FS	*30.00 FS
77	1		*SET REAR FENDER INNER COWLING CLIPS LH	Not Necessary	50.00 FS	*- FS
78	1		*SET REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
79	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
80	1		*FRONT BONNET SEALANT	Not Necessary	150.00 FS	*- FS
81	1		*FRONT FENDER LH SEALANT	Not Necessary	150.00 FS	*- FS
82	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	150.00 FS	*- FS
83	1		*FRONT DOOR LH SEALANT	Not Necessary	150.00 FS	*- FS
84	1		*REAR DOOR LH SEALANT	Not Necessary	150.00 FS	*- FS
85	1		*REAR FENDER LH SEALANT	Not Necessary	150.00 FS	*- FS
86	1		*REAR BOOTLID SEALANT	Not Necessary	150.00 FS	*- FS
87	1		*REAR END PANEL SEALANT	Not Necessary	150.00 FS	*- FS
88	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	150.00 FS	*- FS
89	1		*RADIATOR COOLANT	Not Necessary	100.00 FS	*- FS
90	1		*FRONT WHEEL RIM LH	Cut	550.00 FS	*550.00 FS
91	1		*FRONT TYRE LH	Not Necessary	350.00 FS	*- FS
92	1		*REAR WHEEL RIM LH	Not Necessary	550.00 FS	*- FS
93	1		*REAR TYRE LH	Not Necessary	350.00 FS	*- FS
94	1		*SET REAR BUMPER REVERSE SENSOR	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	32,845.04	4,069.55
- List Item Discount on L Items 25.00/25.00% (\$)	7,211.26	864.89
Total Parts (\$)	25,633.78	3,204.66

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, REMOVE & REFIX PARTS	New	2,000.00	500.00
2	TO SPRAY PAINT AFFECTED AREAS	New	1,800.00	600.00
3	WIRING & BULB CHECK	New	100.00	0.00
4	TO TRANSFER BOOTLID MECHANISM	New	150.00	0.00
5	TO TRANSFER FRONT DOOR LH MECHANISM	New	150.00	60.00
6	TO TRANSFER REAR DOOR LH MECHANISM	New	150.00	0.00
7	TO REMOVE & REFIX REAR BOOTLID CAMERA	New	150.00	0.00
8	TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR	New	120.00	0.00
9	TO SEND FOR DIAGNOSTIC AND RESET CONTROL UNIT. PROGRAMMING & CALIBRATION	New	480.00	0.00
10	TO APPLY ANTI RUST ON AFFECTED PARTS	New	150.00	30.00
11	TO REMOVE & REFIX INTERIOR UPHOLSTRY TO FACILITATE REPAIRS	New	150.00	0.00
12	TO REMOVE & REFIX REAR WINDSCREEN GLASS	New	150.00	0.00
13	TO CONDUCT WATER LEAK TEST	New	100.00	0.00
14	TO REMOVE & REFIX FRONT UNDERCARRIAGE	New	250.00	0.00
15	TO REMOVE & REFIX REAR UNDERCARRIAGE	New	500.00	0.00
16	TO CONDUCT FOUR WHEEL ALIGNMENT	New	150.00	80.00
17	TO REMOVE & REFIX PETROL TANK TO FACILITATE REPAIRS	New	250.00	0.00
Gross Labour Cost (S\$)			6,800.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >