

doc ER

P1140XV

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875
Tel: 93290237 Email: claims_rar@bifrostauto.com

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : SKT 4208G
Made : Toyota
Model : Corolla Altis 1.6 Auto
Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front Bumper	1	\$ 582.89	\$ <i>de</i> 582.89
2	Front Bumper Side Retainer RH	1	\$ 52.50	\$ X 52.50
3	Front Bumper Side Retainer LH	1	\$ 52.50	\$ X 52.50
4	Front Bumper Fog Lamp LH	1	\$ 183.60	\$ X 183.60
5	Front Bumper Fog Lamp Garnish LH	1	\$ 91.20	\$ X 91.20
6	Front Bumper Reinforcement	1	\$ 395.20	\$ X 395.20
7	Front Bumper Lower Grille	1	\$ 198.50	\$ X 198.50
8	Front Headlamp Assembly RH	1	\$ 528.60	\$ X 528.60
9	Front Headlamp Assembly LH	1	\$ 528.60	\$ X 528.60
10	Front Grille	1	\$ 316.60	\$ X 316.60
11	Front Grille Emblem	1	\$ 65.00	\$ X 65.00
12	Front Support Panel	1	\$ 591.60	\$ X 591.60
13	Front Bonnet	1	\$ 845.10	\$ X 845.10
14	Front Bonnet Hinge RH	1	\$ 62.00	\$ X 62.00
15	Front Bonnet Hinge LH	1	\$ 62.00	\$ X 62.00
16	Front Fender LH	1	\$ 498.10	\$ <i>de</i> 498.10
17	Front Fender Emblem LH	1	\$ 55.90	\$ <i>de</i> 55.90
18	Front Fender Inner Cowling LH	1	\$ 145.60	\$ X 145.60
19	Front Shock Absorber LH	1	\$ 430.40	\$ X 430.40
20	Front Knuckle Arm LH	1	\$ 427.20	\$ X 427.20
21	Front Knuckle Arm Bearing LH	1	\$ 203.90	\$ X 203.90
22	Front Lower Arm LH	1	\$ 381.60	\$ X 381.60
23	Front Tie Rod LH	1	\$ 206.80	\$ X 206.80
24	Steering Rack And Pinion	1	\$ 1,970.40	\$ X 1,970.40
25	Front Drive Shaft LH	1	\$ 1,842.60	\$ X 1,842.60
26	Rocker Panel Garnish LH	1	\$ 765.10	\$ <i>de</i> 765.10
27	Front Door LH 1135.30	1	\$ 1,102.80	\$ <i>de</i> 1,102.80
28	Front Door Side Mirror LH 959.80	1	\$ 599.80	\$ <i>de</i> 599.80
29	Front Door Upper Hinge LH	1	\$ 80.30	\$ X 80.30
30	Front Door Lower Hinge LH	1	\$ 80.30	\$ X 80.30
31	Front Door Checker LH	1	\$ 62.10	\$ X 62.10
32	Front Door Inner Lock LH	1	\$ 324.60	\$ X 324.60

All X-nn

561.85

374.10

de

33	Front Door Inner Trim Board LH	1	\$	668.70	\$ X	668.70
34	Front Door Weatherstrip LH	1	\$	164.40	\$ X	164.40
35	Front Door Window Glass Regulator LH	1	\$	263.20	\$ X	263.20
36	Front Door Window Glass Regulator Motor LH	1	\$	657.40	\$ X	657.40
37	Front Door Window Outer Moulding LH	1	\$	142.60	\$ X	142.60
38	Rear Fender LH	1	\$	982.40	\$ X	982.40
39	Rear Fender Inner Cowling LH	1	\$	110.45	\$ X	110.45
40	Rear Fender Air Vent LH	1	\$	138.00	\$ X	138.00
41	Rear Windscreen Glass Outer Moulding	1	\$	123.30	\$ ✓	123.30
42	Rear Door LH	1	\$	1,212.70	\$ X	1,212.70
43	Rear Door Inner Lock LH	1	\$	482.40	\$ X	482.40
44	Rear Door Black Tape LH	1	\$	44.00	\$ ✓	44.00
45	Rear Door Glass Outer Moulding LH	1	\$	113.10	\$ X	113.10
46	Rear Door Outer Handle LH	1	\$	172.50	\$ X	172.50
47	Rear Door Weatherstrip LH	1	\$	173.50	\$ X	173.50
48	Rear Door Inner Trim Board LH	1	\$	796.70	\$ X	796.70
49	Rear Door Power Window Regulator LH	1	\$	214.30	\$ X	214.30
50	Rear Door Power Window Motor LH	1	\$	619.40	\$ ✓	619.40
51	Rear Door Upper Hinge LH	1	\$	91.30	\$ X	91.30
52	Rear Door Lower Hinge LH	1	\$	91.00	\$ X	91.00
53	Rear Shock Absorber LH	1	\$	220.30	\$ X	220.30
54	Rear Wheel Hub Bearing LH	1	\$	365.90	\$ X	365.90
55	Rear Axle	1	\$	3,444.50	\$ X	3,444.50
56	Rear Bumper	1	\$	495.20	\$ X	495.20
57	Rear Bumper Side Retainer RH	1	\$	60.00	\$ X	60.00
58	Rear Bumper Side Retainer LH	1	\$	60.00	\$ X	60.00
59	Rear Bumper Reflector LH	1	\$	60.40	\$ X	60.40
60	Rear End Panel	1	\$	670.00	\$ X	670.00
61	Rear End Panel Top Garnish	1	\$	241.90	\$ X	241.90
62	Rear Taillamp Assembly LH	1	\$	494.00	\$ X	494.00
63	Rear Bootlid	1	\$	793.20	\$ X	793.20
64	Rear Bootlid Taillamp LH	1	\$	353.30	\$ X	353.30
65	Rear Bootlid Emblem	1	\$	61.60	\$ X	61.60
66	Rear Bootlid "Corolla" Emblem	1	\$	48.30	\$ X	48.30
67	Rear Bootlid "Altis" Emblem	1	\$	43.50	\$ X	43.50
68	Rear Bootlid "1.6" Emblem	1	\$	38.70	\$ X	38.70
69	Rear Bootlid Lock	1	\$	399.50	\$ X	399.50
					Parts Sub Total :	\$ 28,845.04
					25% Discount	\$ 7,211.26
					PARTS TOTAL :	\$ 21,633.78

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front Number Plate	1	\$ 50.00	\$ X 50.00
2	Front Bumper Clips - Set	1	\$ 50.00	\$ 50.00 ✓
3	Front Grille Clips - Set	1	\$ 50.00	\$ X 50.00

4	Front Fender Inner Cowling Clips LH - Set	1	\$	50.00	\$ X	50.00
5	Front Door Inner Trim Board Clips LH - Set	1	\$	50.00	\$ X	50.00
6	Rear Door Inner Trim Board Clips LH - Set	1	\$	50.00	\$ X	50.00
7	Rocker Panel Garnish Clips LH - Set	1	\$	50.00	\$ <i>Zone</i>	50.00
8	Rear Fender Inner Cowling Clips LH - Set	1	\$	50.00	\$ X	50.00
9	Rear Bumper Clips - Set	1	\$	50.00	\$ X	50.00
10	Rear End Panel Top Garnish Clips - Set	1	\$	50.00	\$ X	50.00
11	Front Bonnet Sealant	1	\$	150.00	\$ X	150.00
12	Front Fender LH Sealant	1	\$	150.00	\$ X	150.00
13	Front Support Panel Sealant	1	\$	150.00	\$ X	150.00
14	Front Door LH Sealant	1	\$	150.00	\$ X	150.00
15	Rear Door LH Sealant	1	\$	150.00	\$ X	150.00
16	Rear Fender LH Sealant	1	\$	150.00	\$ X	150.00
17	Rear Bootlid Sealant	1	\$	150.00	\$ X	150.00
18	Rear End Panel Sealant	1	\$	150.00	\$ X	150.00
19	Rear Windscreen Glass Sealant	1	\$	150.00	\$ X	150.00
20	Radiator Coolant	1	\$	100.00	\$ X	100.00
21	Front Wheel Rim LH	1	\$	550.00	\$ <i>cut</i>	550.00
22	Front Tyre LH	1	\$	350.00	\$ X	350.00
23	Rear Wheel Rim LH	1	\$	550.00	\$ X	550.00
24	Rear Tyre LH	1	\$	350.00	\$ X	350.00
25	Rear Bumper Reverse Sensor - Set	1	\$	250.00	\$ X	250.00
SPECIAL NETT TOTAL :						\$ 4,000.00

Nos.	LABOUR	TOTAL \$
1	To Panel Beat, Remove & Refix Parts	\$ <i>500</i> 2,000.00
2	To Spray Paint Affected Areas	\$ <i>600</i> 1,800.00
3	Wiring & Bulb Check	\$ X 100.00
4	To Transfer Bootlid Mechanism	\$ X 150.00
5	To Transfer Front Door LH Mechanism	\$ <i>60</i> 150.00
6	To Transfer Rear Door LH Mechanism	\$ X 150.00
7	To Remove & Refix Rear Bootlid Camera	\$ X 150.00
8	To Remove & Refix Rear Bumper Reverse Sensor	\$ X 120.00
9	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ X 480.00
10	To apply anti rust on affected parts	\$ <i>30</i> 150.00
11	To Remove & Refix Interior Upholstry to facilitate repairs	\$ X 150.00
12	To Remove & Refix Rear Windscreen Glass	\$ X 150.00
13	To Conduct Water Leak Test	\$ X 100.00
14	To Remove & Refix Front Undercarriage	\$ X 250.00
15	To Remove & Refix Rear Undercarriage	\$ X 500.00
16	To Conduct Four Wheel Alignment	\$ <i>680</i> 150.00
17	To Remove & Refix Petrol Tank to facilitate repairs	\$ X 250.00
LABOUR TOTAL :		\$ 6,800.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

PARTS TOTAL :	\$	21,633.78
SPECIAL NETT TOTAL :	\$	4,000.00
LABOUR TOTAL :	\$	6,800.00
GRAND TOTAL :	\$	<u>32,433.78</u>

Taufik 97495746
'WP' 15/9/77 @ 440pm
L/S Resurvey after repair
taufik @ khantoun
4 days