

Your Ref : D21MFL0000447\_01

Date: 30<sup>th</sup> Sep 2022

Our Ref : CS/GRB22009042/Kcy3m4

**M/s India International Insurance PL**

64 Cecil Street  
#05-02 IOB Building  
Singapore 049711  
(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SLR 7284P  
ACCIDENT ON 12/09/2022**

Instruction was received to inspect the vehicle Reg. No. SLR 7284P. The inspection was conducted on 14/09/2022 at the premises of M/s Esteem Performance Pte Ltd, 176 Sin Ming Drive #01-14 Sin Ming Autocare, Singapore 575721.

The following vehicle information was recorded:

Registration Number	: SLR 7284P
Make/Model	: Honda Vezel Hybrid 1.5X A
Year of Registration	: 2017
Body Colour	: Metallic Green
Chassis Number	: RU31222484
Engine Capacity	: 1496 cc

The vehicle sustained damages at the front portion. The Estimated repair cost of such vehicle is S\$45,000.00 (Sin Dollars: Forty Five Thousand only.) (Details see photographs enclosed)

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as **"Total Loss"**.

(a) If the vehicle to be "Total Loss"

Market Value	S\$ 66,000.00 (est)	
<i>Less: LTA Reimbursement Value (RV)</i>	<i>(S\$ 26,790.00)</i>	
	<hr/>	
Nett Liability	S\$ 39,210.00	
		S\$ 39,210.00

(b) If the vehicle to be "Repair"

Repair Cost (Est)	S\$ 45,000.00	
	<hr/>	
Nett Liability		S\$ 45,000.00

(a) – (b) = (S\$ 5,790.00)

The amount of estimated saving of S\$5,790.00 if the vehicle to be written off as **"Total Loss"** instead of to be repair.

Vehicle Inspected By:



KONG SENG CHEONG  
Licensed Appraiser



K.K.LAU  
MSc(Eng M), B Eng(Hons), PEng(UK),  
MASME(USA), B Bus(Aust),MBA(UK),  
IEng(UK), MIIE(mech), MinstAEA, MFIEA,  
MIRTE,MIMI,MSAE,MCIARD, AM,NIJAAR(USA),  
AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.