

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0798/2022/EQ
DATE : 14-Sep-22
WIP : 41813

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 20/09/2022

YOUR INSURED VEH NO : SMC 9932 G

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR ANG ZHIHAO
ADDRESS : BLK 269B QUEEN STREET
#09-274
SINGAPORE 182269
TELEPHONE : HP +65 85884850
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5125806032
VEHICLE NO : **EH 1514 B**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 18/3/2021
ENGINE NO : DEM 028718
CHASSIS NO : WAUZZZF55MA018821
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Sep-22
PLACE OF ACCIDENT : EAST COAST CARPARK F3

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE EH 1514 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$	1,600.00	
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$	1,200.00	
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	5,600.00	
TOTAL LABOUR CHARGES		:	\$ 9,280.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE EH 1514 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET.	\$	3,500.00	
7	TO APPLY LTA APPROVAL FOR REMOVE AND RENEW OPC SEAL.	S/N \$	280.00	
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	\$ 13,252.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. EH 1514 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,493.00	
2	FRONT BUMPER SECURING STRIP	2	\$ 79.00	
3	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 293.00	
5	FRONT BUMPER SPOILER	1	\$ 599.00	
6	FRONT BUMPER AIR GUIDE - RH	1	\$ 72.00	
7	FRONT BUMPER CLOSING ELEMENT	1	\$ 293.00	
8	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 151.00	
9	FRONT BUMPER TRIM - RH	1	\$ 54.00	
10	FRONT BUMPER TRIM - CENTER	1	\$ 127.00	
11	RADIATOR GRILLE	1	\$ 1,881.00	
12	RADIATOR GRILLE BRACKET	1	\$ 19.00	
13	RADIATOR GRILLE SECURING PLATE	1	\$ 12.00	
14	FRONT BUMPER FOAM FILLER PIECE	1	\$ 163.00	
15	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00	
16	FRONT BUMPER REINFORCEMENT BEAM BRACKET - RH	1	\$ 254.00	
17	FRONT BUMPER GUIDE SECTION - RH	1	\$ 41.00	
18	FRONT BUMPER TOP COVER	1	\$ 143.00	
19	CAUTION SIGN STICKER	1	\$ 16.00	
20	AIR CONDITIONER STICKER	1	\$ 9.00	
SUB TOTAL SPARE PARTS		:	\$ 7,817.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. EH 1514 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	LOCK CARRIER BRACKET	1	\$ 154.00	
22	LOCK CARRIER BRACKET SUPPORT - LH / RH	2	\$ 64.00	
23	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$ 532.00	
24	FRONT BUMPER WIRING SET	1	\$ 449.00	
25	HORN LOW TONE - RH	1	\$ 139.00	
26	HORN BRACKET - RH	1	\$ 33.00	
27	FRONT FENDER - RH	1	\$ 1,189.00	
28	FRONT FENDER ATTACHMENT PARTS	1	\$ 55.00	
29	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 83.00	
30	FRONT FENDER BRACKET - RH	1	\$ 41.00	
31	FRONT FENDER BRACE - RH	1	\$ 132.00	
32	FRONT FENDER RIVET	6	\$ 23.00	
33	FRONT FENDER CHROME TRIM - RH	1	\$ 171.00	
34	FRONT WHEEL HOUSING LINER - RH	1	\$ 299.00	
35	FRONT WHEEL SPOILER - RH	1	\$ 82.00	
36	FRONT WHEEL SPOILER TRIM - RH	1	\$ 40.00	
37	FRONT FENDER STONE CHIP GUARD - RH	1	\$ 57.00	
38	FRONT FENDER LOWER BRACKET - RH	1	\$ 27.00	
39	FRONT FENDER TOP LEDGE COVER - RH	1	\$ 40.00	
40	FRONT FENDER LEDGE COVER - RH	1	\$ 18.00	
SUB TOTAL SPARE PARTS		:	\$ 3,628.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. EH 1514 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	HEADLIGHT COVER - RH	1	\$ 49.00	
42	BONNET	1	\$ 3,491.00	
43	BONNET ATTACHMENT PARTS	1	\$ 128.00	
44	BONNET IMPACT PROTECTION - LH / RH / CENTER	3	\$ 62.00	
45	BONNET SOUND ABSORBER	1	\$ 382.00	
46	BONNET STRIKER - RH	1	\$ 56.00	
47	BONNET LOCK	1	\$ 228.00	
48	BONNET BOWDEN CABLE - CENTER	1	\$ 64.00	
49	BONNET RELEASE LEVER	1	\$ 15.00	
50	LOCK CARRIER	1	\$ 1,478.00	
51	LOCK CARRIER SUPPORT - RH	1	\$ 43.00	
52	CHARGE AIR COOLER	1	\$ 654.00	
53	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00	
54	A/C CONDENSER	1	\$ 683.00	
55	READY-MIX COOLANT	6	\$ 297.00	
56	RADIATOR AIR DUCT - RH	1	\$ 36.00	
57	RADIATOR AIR DUCT - RH	1	\$ 19.00	
58	RADIATOR AIR GUIDE - UPPER	1	\$ 19.00	
59	RADIATOR AIR GUIDE - LOWER	1	\$ 25.00	
60	FRONT NO PLATE	S/N	\$ 100.00	
61	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 19,695.00	
TOTAL LABOUR CHARGES		:	\$ 13,252.00	
GRAND TOTAL		:	\$ 32,947.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT