

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: G13K8022C
 at Workshop m/s 1myam
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: G13K8022C Yr Regn: 26/11/20
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA /
 Make: Toyota hiace D42-8c 2754
 Colour: silver A/C: Insured / Std / NI / NA
 Sp. Reading: 60082 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: GDM 2012014182
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: ~~In order / Jammed / Leaked / Burnt~~ or **Affected**
 Brake: ~~In order / Jammed / Leaked / Burnt~~ or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195-215 35
 R: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.
 Bal. or Market Value: \$84k.
 IDAC Accident Rpt: Consistent?: Yes or No
 GIA / PR Seen: Consistent?: Yes or No
 Est. Repairs: 20 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front 6 mm Rear 6 mm
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 12/09/22 D.O.I. 14/19/22
 Survey held at _____

CA / REV / REP. / 24 HRS C 5532
 Date: _____ Person Contacted: 27A 25822
 Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.
N/S for, N/S body & all N/S cracked

12/10/22 H/S \$25,000 informed shown.
 OI accident scene photo can see TP front windscreen cracked.
 12/10/22 Marcus confirmed Lump Sum \$ 25,000 and 20 days
 (Red, 25269.71, 50%)

Date/Time, File Pass to? : Preli. Report
 1) 17/10/22 : Final Report

Days Of Repair: 20
 Resurvey No. of Trip: 3

Survey Fee:	
Transportation:	
_____ S + RS, _____ SI	
_____ Photos	
_____ Others	
_____ Weekend (\$ _____)	
TOTAL	

Report Format :
 Lump Sum / I.B.I.: (\$ 25000)

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

> **Back to OneMotoring****Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	559Z
Vehicle Details	
Vehicle No.:	GBK8022C
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Sep 2022
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DX 2.8 AUTO
Primary Colour:	Silver
Manufacturing Year:	2020
Engine No.:	1GD8609816
Chassis No.:	GDH2012014182
Maximum Power Output:	-
Open Market Value:	\$35,682.00
Original Registration Date:	26 Nov 2020
First Registration Date:	26 Nov 2020
Transfer Count:	0
Actual ARF Paid:	\$1,785.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 Nov 2030
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$31,502.00
COE Rebate Amount:	\$25,822.00
Total Rebate Amount:	\$25,822.00

The information contained herein is correct as at 13 Sep 2022

OK




Best of Indian art, shipped directly to Singapore

[EXPLORE NOW](#)

Post an Advertisement
 Sell it yourself! Advertise it at just **\$68 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

2016 Mazda 3 HB. Lowest Price.



Sporty car with Sport Rim and Michelin Tyres. Full Loan, Inhouse Loan Available. ABS Bus Pte Ltd StarAd

Republic Auto | **CERTIFIED PRE-OWNED MERCEDES BENZ**



[VIEW OUR CARS](#)

Sort by Date Posted 20 results/page

15 vehicles



toyota hiace dx

Any Category

Advanced Search

Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection

toyota hiace dx Any Any **2020** Any Any Any Any **Available**



Toyota Hiace 2.8A DX **\$82,800** \$11,070 /yr 05-Mar-2020 2,754 cc - Van **Available**
Fuel Type: Diesel
 The Perfect Van for your business needs. Incredible performance coupled with good fuel economy from the diesel engine. Fully suitable f...
 Bell KSL Auto Pte Ltd
 Posted: 13-Sep-2022

PREMIUM AD



Toyota Hiace 2.8A DX **\$82,800** \$11,310 /yr 07-Jan-2020 2,754 cc - Van **Available**
Fuel Type: Diesel
 The Perfect Van For Your Business Needs. Incredible Performance Coupled With Good Fuel Economy From The Diesel Engine. Fully Suita...
 Bell KSL Auto Pte Ltd
 Posted: 13-Sep-2022

PREMIUM AD




Toyota Hiace 2.8A DX **\$88,800** \$11,250 /yr 05-Aug-2020 2,754 cc 20,199 km Van **Available**
Fuel Type: Diesel
 The Perfect Van For Your Business Needs. Incredible Performance Coupled With Good Fuel Economy From The Diesel Engine. Fully Suita...
 Bell KSL Auto Pte Ltd
 Posted: 13-Sep-2022

PREMIUM AD



Toyota Hiace 2.8A DX **\$86,800** \$10,990 /yr 06-Aug-2020 2,754 cc - Van **Available**
Fuel Type: Diesel
 1 owner vehicle. Original paintwork and original condition like a new van. owner sell because lack of manpower to drive and used to be...
 ABS Bus Pte Ltd
 Posted: 12-Sep-2022

PREMIUM AD



Enjoy comfort With Genuine Toyota Absorber
 Toyota Genuine Parts, Shock Absorber and other related parts
 More info about this product



Toyota Hiace 2.8A DX **\$85,800** \$10,580 /yr 23-Oct-2020 2,754 cc 32,984 km Van **Available**
Fuel Type: Diesel
 Best deals with us. Low mileage and smooth transmission. 3 month warranty, fully serviced before handover + additional 2 free servicin...
 Skylink Auto Pte Ltd
 Posted: 09-Sep-2022

PREMIUM AD



Toyota Hiace 2.8A DX **\$82,888** \$11,200 /yr 06-Feb-2020 2,754 cc 55,000 km Van **Available**
Fuel Type: Diesel
 Cheapest in market! 5 door Hiace come with 1 year warranty and 2 free servicing!
 Posted: 08-Sep-2022

PREMIUM AD

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-47 Synergy@KB, Singapore 417800

HP : 9748 9940 Shawn Tan

Email: shawn7530@hotmail.com

Not Authorized
 del
 14/9/22
 2/s \$ 25,000
 20 Sep 2022
 20 days.

Vehicle No.: GBK 8022 C

Model: TOYOTA HIACE

QTY	DESCRIPTION	AMT S\$
	<u>List Items</u>	
1	Front headlamp -LH <i>one</i>	\$ 2,680.00
1	Front bumper <i>Torn</i>	\$ 862.16
2	Front bumper side brackets <i>n/s one</i>	\$ 178.60 <i>IPC</i>
1	Gear lever housing top <i>one</i>	\$ 455.20
1	Gear lever housing lower <i>one</i>	\$ 525.20
1	Front dashboard <i>11</i>	\$ 955.85 <i>X</i>
1	Front dashboard side cover <i>del/torn</i>	\$ 242.80
1	Front dashboard inner air vent -side <i>11</i>	\$ 89.50 <i>X</i>
1	Front wheel rim <i>115</i>	\$ 480.00 <i>SOSAN</i>
1	Front rim cover <i>115</i>	\$ 185.00
1	Front wheel hub <i>Dis</i>	\$ 315.90
1	Front wheel bearing <i>Dye</i>	\$ 133.95
1	Front shock absorber <i>Surf</i>	\$ 135.80
1	Front knuckle arm <i>one</i>	\$ 489.60
1	Front lower arm <i>Tw1</i>	\$ 223.30
1	Front stay bar <i>Surf</i>	\$ 189.50
1	Front top arm <i>Surf</i>	\$ 653.00
1	Power steering rack assy <i>Surf</i>	\$ 1,895.62 <i>X</i>
1	Power steering rack crossmember <i>Surf/Tw1</i>	\$ 1,685.00
1	Front anti roll bar <i>11</i>	\$ 335.60 <i>X</i>
1	Front anti roll bar link <i>11</i>	\$ 89.60 <i>X</i>
1	Engine mounting -LH <i>11</i>	\$ 285.20 <i>X</i>
1	Battery tray <i>one</i>	\$ 168.00
1	Front windscreen glass <i>one</i>	\$ 1,279.50
1	Front windscreen moulding <i>all</i>	\$ 129.80
1	Front door -LH <i>Dis</i>	\$ 1,670.00
1	Front door checker <i>11</i>	\$ 35.80 <i>X</i>
1	Front door glass <i>one</i>	\$ 440.94
1	Front door glass outer moulding <i>Surf</i>	\$ 133.95
2	Front door hinges <i>11</i>	\$ 155.96 <i>X</i>
1	Front door inner board <i>del/torn</i>	\$ 897.50
1	Front door lock <i>no/ym</i>	\$ 272.50
1	Front door outer handle <i>Surf</i>	\$ 163.50
1	Front door speaker <i>one</i>	\$ 185.00
1	Front door glass stay <i>Surf</i>	\$ 78.00
1	Front door regulator <i>Surf</i>	\$ 211.36
1	Front door regulator motor <i>Surf</i>	\$ 489.55
		\$ 19,397.74

List Items				
1	Front door rubber lower	Torn	\$	155.20 ✓
1	Front door rubber	Torn	\$	190.05 ✓
1	Front door side mirror	SNW	\$	450.60 ✓
1	Front rear pillar inner garnish -top	DJS	\$	123.50 ✓
1	Front rear pillar inner garnish -lower	DJS	\$	195.20 ✓
1	Front rear pillar	Body RD	\$	822.59 ✓
1	Front rear pillar inner member	Body RD	\$	685.00 ✓
1	Front wheel arch panel	SUC	\$	569.20 ✓
1	Front wheel arch panel top garnish	DJS	\$	144.90 ✓
1	Front wheel arch panel seal	Torn	\$	122.60 ✓
1	Front step panel	R	\$	139.60 X
1	Front step panel garnish -LH	Torn	\$	105.95 ✓
1	Sliding door -LH	DJS	\$	1,611.00 ✓
1	Sliding door lock -front	DJS	\$	282.50 ✓
1	Sliding door lock striker	Bent	\$	168.50 ✓
1	Sliding door rubber	Torn	\$	287.00 ✓
1	Sliding door inner board	Torn	\$	444.00 ✓
1	Sliding door centre roller	Bent/Twl	\$	223.50 ✓
1	Sliding door centre track	11	\$	483.12 X
1	Sliding door outer handle	scr/Twl	\$	198.10 ✓
1	Sliding door inner pull handle	11	\$	155.80 X
1	Sliding door lock -rear	JM	\$	252.40 ✓
1	Sliding door top roller	Bent	\$	189.60 ✓
1	Sliding door lower roller	Bent	\$	173.50 ✓
1	Sliding door glass	Shotted	\$	828.50 ✓
1	Sliding door inner step panel	DJS	\$	1,150.20 ✓
1	Sliding door inner step panel top moulding	NK	\$	238.50 X
1	Rocker panel -LH	Bent/DJS	\$	785.00 ✓
1	Roof top panel	R	\$	1,895.20 X
1	Roof top panel inner trim -front	worped	\$	1,219.80 ✓
1	Roof top panel inner trim -rear	worped	\$	1,080.50 ✓
1	Roof top panel inner trim air vent	11	\$	225.00 X
1	Front passenger seat assy	Bent/Twl	\$	2,250.00 ✓
1	Front seat back reinforcement bar	Bent	\$	385.00 ✓
1	Rear side panel inner member	R	\$	1,485.00 X
1	Fuel lid cover	DJS	\$	155.00 ✓
1	Fuel tank neck pipe	Bent/Twl	\$	382.00 ✓
1	Front floor top panel	Body RD/SUC	\$	1,250.80 ✓
1	Front floor panel	R	\$	1,480.50 X
1	Rear floor front panel	DJS/SUC	\$	1,250.80 ✓
			\$	43,632.95
			Less 25%	\$ 10,908.24
				\$ 32,724.71

Special Nett Items

1	Front seat lower wooden board set	NS	\$	2,500.00	X
1	Front tyre	1LS PUN LP 200 60%	\$	400.00	120
1	Battery	DO/RE	\$	350.00	100
1	ERP IU bracket	ALL	\$	40.00	20
1	Front number plate with holder	11	\$	50.00	X
1	Front windscreen sealant	ALL	\$	60.00	40
1	Front windscreen sticker (1 set)	ALL	\$	350.00	100
1	Front door lettering sticker	ALL	\$	45.00	30
1	Sliding door sticker (1 set)	ALL	\$	350.00	100
1	Front floor panel top map	NT	\$	450.00	X
1	Front floor panel rear map	NT	\$	450.00	X
1	Rear floor panel top map mat	DIS	\$	450.00	✓
1	Rear floor panel top wooden board	DIS	\$	750.00	600
1	Rear floor panel insulator	ALL	\$	200.00	150
			\$	<u>6,445.00</u>	

S/N. Labour Charges

1	To check wiring and reset headlamps focusing.	\$	120.00	30
2	To remove, refit roof top lining, cushion seat and interior upholstery.	\$	250.00	100
3	To remove and refit fuel tank assembly with all attachments.	\$	250.00	60
4	To remove and refit front undercarriage.	\$	500.00	380
5	To conduct wheel alignment.	\$	200.00	60
6	To lift-up engine to assist repair.	\$ 11	500.00	X
7	To remove and refit dashboard.	\$	250.00	200
8	To remove and refit front windscreen glass.	\$	180.00	120
9	To remove and refit quarter glass to assist repair.	\$	150.00	60
10	To remove, refit door fittings and replace damaged parts, transfer all fittings to new door.	\$	400.00	100
11	To apply undercoating.	\$	300.00	120
12	Panel beating.	\$	4,000.00	3000
13	To re-spray painting on the affected areas.	\$	3,500.00	1500
14	To diagnose erase fault memory after repair.	\$ 11	500.00	X
		\$	<u>11,100.00</u>	

Grand Total : \$ 50,269.71

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

7-31713-64
47
23785-23
1760
5730
31275-23