



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref:	CS/ASM22009045/Uny3e2
8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		Date:	19/10/2022
ATTN: TEO KITTY		Code:	ASM
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YL 1788U	Veh. Inspected	GBK 8022C
Policy No.	GA607824	Coverage (\$)	0.00
Claim No.	S2M04AZW	Excess (\$)	0.00
Assign From	TEO KITTY	Assign Date	14/09/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE DX 2.8 (A)	c.c	2754
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	GDH2012014182	Colour	SILVER
Odometer	60082 KM	Steering	AFFECTED
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	BRIDGESTONE	6 mm
L/H Front Tyre	195 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	195 R15	DUNLOP	6 mm
L/H Rear Tyre	195 R15	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION, N/S BODY AND FRONT WINDSCREEN CRACKED. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/09/2022	Inspection Date	14/09/2022
Survey held at	IMPERIUM AUTOMOTIVE 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		20 Working Days	