

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT/22009048/4943

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBP7935Z

at Workshop m/s

BMH

of

Insured:

YA4395Z

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

619k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lump Sum:

1-3.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

075h

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 2084

Veh No:

FBP7935Z

Yr Regn:

13/06/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda NC750XA c.c 745

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading

44793

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JH2RC90AXKK301918

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

120/70ZR17

R:

160/60ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

PIR

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

09/09/22

D.O.I.

14/09/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

0073k.

21/11/22

no second hand parts
P/P 4656.90
(no lump sum)

Raymond (Red 5074.10, 52%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 41597

- Rev. 1

CHINA TAIPING INSURANCE (S) PTE LTD
105 CECIL STREET
#18-00 / 19-00
THE OCTAGON
S'PORE 069534
ATTN: MOTOR CLAIMS DEPT

DATE : 13/09/2022
CLAIM NO. : 12000
POLICY NO. : PNMC2020-00001734-02
FROM : RAYMOND

VEHICLE NO. : FBP7935Z
MAKE/MODEL : HON / NC750XA

Not Authorised
11P 9
the phle AFA my
H day
14/9/22

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	*R381C*CANDY CHROMOSPHERE RED - (REPORTED BY MECHANIC)	REPLACE	1.00	\$383.00, <i>one</i>	383.00 ✓
2	*R381C*CANDY CHROMOSPHERE RED - (REPORTED BY MECHANIC)	REPLACE	1.00	\$383.00, <i>one</i>	383.00 ✓
3	ALIGNMENT BODY / FRAME P/N: 29844 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$420.00, <i>ANX</i>	420.00
4	BOX REAR (SHAD) SH39 P/N: 62127 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$455.00, <i>350</i>	455.00
5	BOX SIDE (SHAD) SH23 P/N: 72278 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$630.00, <i>grad</i>	630.00 ✓
6	BRACKET BOX REAR (SHAD) P/N: 60952 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$630.00, <i>grad</i>	630.00 ✓
7	BRACKET SIDE BOX 3P - (REPORTED BY MECHANIC)	REPLACE	1.00	\$700.00, <i>sw/lin</i>	700.00 ✓
8	CHAIN DRIVE ASSY (520-120) P/N: 49671 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$255.00, <i>x 12</i>	255.00 X
9	COVER CENTER SEAT P/N: 69686 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$84.00, <i>x 12</i>	84.00

*41597 *

3276

bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
10	FENDER REAR B P/N: 57702 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$362.00	362.00
11	GASKET MUFFLER P/N: 61399 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$24.00	24.00
12	LABEL CHAIN ADJUSTER P/N: 73566 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$26.00	26.00
13	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	10.00	\$63.00	630.00
14	LAMP SIGNAL REAR LH P/N: 73561 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$182.00	182.00
15	LAMP SIGNAL REAR RH P/N: 73559 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$182.00	182.00
16	LIGHT ASSY LICENSE P/N: 74730 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$104.00	104.00
17	MUDGUARD REAR P/N: 73178 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$138.00	138.00
18	MUFFLER COMP P/N: 73556 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$840.00	840.00
19	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$26.00	26.00
20	PLUG HOLE P/N: 74731 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00	10.00
21	PLUG, HANDLE COVER (LOWER) P/N: 66741 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00	10.00
22	RIVET P/N: 29942 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$6.00	12.00
23	RUBBER MOUNT LAMP SIGNAL LH P/N: 73564 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$42.00	42.00
24	RUBBER MOUNT LAMP SIGNAL RH P/N: 73557 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$42.00	42.00

*41597 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
25	RUBBER TAILLIGHT - (REPORTED BY MECHANIC)	REPLACE	2.00	\$12.00	24.00
26	SWINGARM SUB ASSY P/N: 58570 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$2,334.00	2,334.00
27	TAIL LIGHT ASSY P/N: 73662 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$319.00	319.00
28	TYRE 160/60-17 (PIRELLI) ROSSO 3 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$276.00	276.00
29	TRANSPORT CHARGES (MOTORCYCLE) CLASS 2 P/N: 45836	Supply/Install	1.00	\$70.00	70.00
SUB TOTAL					\$9,593.00
GST @ 7 %					\$671.51
GRAND TOTAL (SGD)					\$10,264.51

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9-4641
102
4176.90
480
4656.90

*41597 *

bizSAFE₃





BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

CHINA TAIPING INSURANCE (S) PTE LTD
105 CECIL STREET
#18-00 / 19-00
THE OCTAGON
S'PORE 069534
ATTN: MOTOR CLAIMS DEPT

NO. : 41597

- Rev. 2

DATE : 13/09/2022
CLAIM NO. : 12000
POLICY NO. : PNMC2020-00001734-02

FROM : RAYMOND

VEHICLE NO. : FBP7935Z
MAKE/MODEL : HON / NC750XA

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	*R381C*CANDY CHROMOSPHERE RED	REPLACE	1.00	\$383.00	344.70
				Disc %: 10.00	
	- (REPORTED BY MECHANIC)				
2	*R381C*CANDY CHROMOSPHERE RED	REPLACE	1.00	\$383.00	344.70
				Disc %: 10.00	
	- (REPORTED BY MECHANIC)				
3	BOX REAR (SHAD) SH39	REPLACE	1.00	\$350.00	315.00
	P/N: 62127			Disc %: 10.00	
	- (REPORTED BY MECHANIC)				
4	BOX SIDE (SHAD) SH23	REPLACE	1.00	\$630.00	567.00
	P/N: 72278			Disc %: 10.00	
	- (REPORTED BY MECHANIC)				
5	BRACKET BOX REAR (SHAD)	REPLACE	1.00	\$630.00	567.00
	P/N: 60952			Disc %: 10.00	
	- (REPORTED BY MECHANIC)				
6	BRACKET SIDE BOX 3P	REPLACE	1.00	\$700.00	630.00
				Disc %: 10.00	
	- (REPORTED BY MECHANIC)				
7	FENDER REAR B	REPLACE	1.00	\$362.00	325.80
	P/N: 57702			Disc %: 10.00	
	- (REPORTED BY MECHANIC)				
8	LABOUR	Supply/Install	1.00	\$400.00	400.00
	P/N: 06766				
	- LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.				
9	LAMP SIGNAL REAR LH	REPLACE	1.00	\$182.00	163.80
	P/N: 73561			Disc %: 10.00	
	- (REPORTED BY MECHANIC)				

*41597 *

bizSAFE₃



Quotation Nos. : 41597 - Rev. 2

S/N	Description	Action	Qty	Unit Price	Amount
10	LAMP SIGNAL REAR RH P/N: 73559 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$182.00 Disc %: 10.00	163.80
11	LIGHT ASSY LICENSE P/N: 74730 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$104.00 Disc %: 10.00	93.60
12	MUDGUARD REAR P/N: 73178 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$138.00 Disc %: 10.00	124.20
13	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$20.00	20.00
14	PLUG HOLE P/N: 74731 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00 Disc %: 10.00	9.00
15	PLUG, HANDLE COVER (LOWER) P/N: 66741 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00 Disc %: 10.00	9.00
16	RIVET P/N: 29942 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$6.00 Disc %: 10.00	10.80
17	RUBBER MOUNT LAMP SIGNAL LH P/N: 73564 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$42.00 Disc %: 10.00	37.80
18	RUBBER MOUNT LAMP SIGNAL RH P/N: 73557 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$42.00 Disc %: 10.00	37.80
19	RUBBER TAILLIGHT - (REPORTED BY MECHANIC)	REPLACE	2.00	\$12.00 Disc %: 10.00	21.60
20	TAIL LIGHT ASSY P/N: 73662 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$319.00 Disc %: 10.00	287.10
21	BRACKET MUDGUARD REAR P/N: 66744	Replace	1.00	\$138.00 Disc %: 10.00	124.20
22	TRANSPORT CHARGES (MOTORCYCLE) CLASS 2 P/N: 45836	Supply/Install	1.00	\$60.00	60.00

SUB TOTAL

\$4,656.90

GST @ 7 %

\$325.98

GRAND TOTAL (SGD)

\$4,982.88

50% deposit required before ordering of parts.

Validity: 30 days

*41597 *



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
	For & on Behalf of				
	BAN HOCK HIN CO PTE LTD			Acknowledge & Accepted By	



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*41597 *

bizSAFE₃



Vehicle Details

Vehicle No.	Make / Model
FBP7935Z	HONDA / NC750XA
Vehicle Type :	Vehicle Attachment 1 :
P00 - Passenger Motorcycle/Autocycle/Moped	No Attachment
Vehicle Scheme :	Chassis No. :
Normal	JH2RC90AXKK301918
Propellant :	Engine No. :
Petrol	RC88E5202270
Motor No. :	Engine Capacity :
-	745 cc
Power Rating :	Maximum Power Output :
-	-
Maximum Laden Weight :	Unladen Weight :
429 kg	220 kg
Year Of Manufacture :	Original Registration Date :
2019	13 Jun 2019
Lifespan Expiry Date :	COE Category :
-	D - Motorcycle
Quota Premium :	COE Expiry Date :
\$3,090.00	12 Jun 2029
Road Tax Expiry Date :	PARF Eligibility Expiry Date :
12 Dec 2022	-
Inspection Due Date :	Intended Transfer Date :
12 Jun 2023	16 Sep 2022
CO2 Emission :	CEV/VES Rebate Utilised Amount :