

Case Details

Case Reference Number : TAX/09/22/2030
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB99K

Company Type : Slides Taxi Pte Ltd
 Estimation ID : EST-19357-1D
 Assigned By : Tan Lee Ge #

Insurance Company Name : EQ Insurance Company Ltd
 Accident Date and Time : 13/09/2022 04:26 AM
 Vehicle Age(In Months) :-

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation							Surveyor Approval							
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	cr
Standard	Main			BUMPER CLIPS (10 PCS)	10	2.40	24.00	25.00	18.00	Replace	10	18.00	Replace	cr
Standard	Main			BUMPER REINFORCEMENT REAR	1	234.70	234.70	25.00	176.02	Replace	0	0	Check	ixi
Standard	Main			ARM SUB-ASSY. RR BUMPER RH	1	157.90	157.90	25.00	118.43	Replace	0	0	Check	ixi
Standard	Main			ARM SUB-ASSY. RR BUMPER LH	1	157.90	157.90	25.00	118.43	Replace	0	0	Check	ixi
Standard	Main			ANTENNA ELECTRICAL LOWER REAR	1	208.10	208.10	10.00	187.29	Replace	0	0	Check	ixi
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	an
Standard	Main			BUMPER SIDE RETAINER RRLH	1	108.70	108.70	25.00	81.53	Replace	0	0	Not Give	ixi
Standard	Main			BUMPER SIDE RETAINER RRRH	1	108.70	108.70	25.00	81.53	Replace	0	0	Not Give	ixi

Standard	Main			BUMPER SEAL, RR LH	1	101.80	101.80	25.00	76.35	Replace	0	0	Not Give	ixi
Standard	Main			BUMPER SEAL, RR RH	1	74.40	74.40	25.00	55.80	Replace	0	0	Not Give	ixi
Standard	Main			BUMPER LIP COVER RRLH	1	93.90	93.90	25.00	70.43	Replace	0	0	Not Give	ixi
Standard	Main			BUMPER LIP COVER RRRH	1	155.40	155.40	25.00	116.55	Replace	0	0	Not Give	ixi
Standard	Main			BUMPER LIP REAR	1	301.90	301.90	25.00	226.42	Replace	0	0	Not Give	ixi

Surveyor Total 2,514.90
 Not Give 20.00
 Lump Sum Dis (%) 20.00
 Final Sur Total 2,011.92

Standard	Main	Portion	Material Number	Part Name	Qty	List Price	Unit(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Price(\$)	Not Give
Standard	Main			UNDER COVER RR SHIELD	1	586.10	755.10	25.00	439.58	Replace	0	0	Not Give
Standard	Main			ASSY, RR FLOOR	1	586.10	755.10	25.00	439.58	Replace	0	0	Not Give
Standard	Main			END PANEL	1	586.10	755.10	25.00	439.58	Replace	1	566.32	Replace
Standard	Main			SPARE TYRE PANEL	1	586.10	755.10	25.00	439.58	Replace	0	0	Not Give
Standard	Main			TAILGATE ASY	1	586.10	755.10	25.00	439.58	Replace	1	0	Repair
Standard	Main			TAILGATE DOOR HINGE LHRH (2 PCS)	2	586.10	755.10	25.00	439.58	Replace	0	0	Not Give
Standard	Main			TAILGATE DOOR LOCK	1	586.10	755.10	25.00	439.58	Replace	0	0	Not Give
Standard	Main			TAILGATE LOCK COVER	1	586.10	755.10	25.00	439.58	Replace	0	0	Not Give
Standard	Main			TAILGATE DOOR WEATHER STRIP	1	586.10	755.10	25.00	439.58	Replace	0	0	Not Give
Standard	Main			TAILGATE OUTSIDE GARNISH	1	586.10	755.10	25.00	439.58	Replace	1	0	Repair
Standard	Main			EMBLEM REAR	1	586.10	755.10	25.00	439.58	Replace	1	51.53	Replace
Standard	Main			LICENSE PLATE LAMP (2 PCS)	2	586.10	755.10	25.00	439.58	Replace	0	0	Not Give
Standard	Main			CAMERA ASSY, TELEVISION, RR	1	586.10	755.10	25.00	439.58	Replace	0	0	Not Give
Standard	Main			NAME PLATE (HYBRID)	1	586.10	755.10	25.00	439.58	Replace	1	44.40	Replace
Standard	Main			NAME PLATE (PRUIS)	1	586.10	755.10	25.00	439.58	Replace	1	52.05	Replace
Standard	Main			NAME PLATE (TOYOTA)	1	586.10	755.10	25.00	439.58	Replace	1	44.40	Replace
Standard	Main			STRIDES LOGO	1	586.10	755.10	25.00	439.58	Replace	1	7.50	Replace
Standard	Main			STICKER DECAL 6558888	1	586.10	755.10	25.00	439.58	Replace	1	21.60	Replace
Standard	Main			3RD BRAKE LAMP	1	586.10	755.10	25.00	439.58	Replace	1	237.00	Replace
Standard	Main			SPOILER REAR	1	586.10	755.10	25.00	439.58	Replace	1	947.78	Replace

Standard	Main	TAIL LAMP BRACKET, RH	1	35.20	35.20	25.00	26.40	Replace	0	0	Not Give	✓
Standard	Main	TAIL LAMP RH	1	618.60	618.60	10.00	556.74	Replace	0	0	Not Give	✓
Standard	Main	TAIL LAMP BRACKET, LH	1	35.20	35.20	25.00	26.40	Replace	0	0	Not Give	✓
Standard	Main	TAIL LAMP LH	1	618.60	618.60	10.00	556.74	Replace	0	0	Not Give	✓

Total Spare Part Cost 9,760.24

Surveyor Total	2 514.90
----------------	----------

James Quinn Nicolson (b. 1906)

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	7,362.60	2,011.92
Total Labour Cost	1,014.00	600.00
Total Spray Painting	1,668.00	700.00
Other	556.00	120.00
Overall Total	10,598.60	3,431.92
Lump Sum Repair Option	☒	☒
Lump Sum Total	10,600.00	3,450.00
Surveyor Approved Amount		3,450.00
No of Repair Days*	6	5
Remarks		
Surveyor Name		Rasul
Signature		
Survey Date	14/09/2022	

Request NBV / Lump sum repair / After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL 0109590 0438 / 010 0004 0009 0000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: