

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

AARON NG YEW KIAN  
 BLK 674B JURONG WEST ST 65 #09-60  
 SINGAPORE 642674

Contact : 85227756

*TP Allianz*  
*Celine*

## TAX INVOICE

Repair Code : CLM17370

Date in : 10/09/2022

Vehicle Num. : SMM7814A

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11116443/L15B4036447

### Parts and Labour Assesment

| Description of part                                              | Qty | Unit Price | Amount   |
|------------------------------------------------------------------|-----|------------|----------|
| REAR BODY EXTENSION RH <i>Repair</i>                             | 1   | 720.00     | + 720.00 |
| REAR BODY EXTENSION UPPER PANEL RH <i>Repair Bulkhead</i>        | 1   | 160.00     | ✓ 160.00 |
| REAR BUMPER <i>Distaloid</i>                                     | 1   | 463.70     | ✓ 463.70 |
| REAR BUMPER BUZZLE SENSOR <i>Am Led</i>                          | 1   | 85.20      | ✓ 85.20  |
| REAR <del>BUMPER</del> INNER TOP GARNISH <i>End Panel Deloid</i> | 1   | 98.00      | ✓ 98.00  |
| REAR BUMPER LOWER COVER <i>Deloid</i>                            | 1   | 250.00     | ✓ 250.00 |
| REAR BUMPER REFLECTOR L/R <i>Am Led</i>                          | 2   | 141.10     | ✓ 282.20 |
| REAR BUMPER SIDE L/R <i>Deloid</i>                               | 2   | 195.00     | ✓ 390.00 |
| REAR BUMPER SIDE RETAINER L/R <i>Am Led</i>                      | 2   | 23.00      | ✓ 46.00  |
| REAR END PANEL <i>Distaloid</i>                                  | 1   | 415.60     | ✓ 415.60 |
| REAR END PANEL ANTENNA SENSOR <i>Am Led</i>                      | 1   | 60.10      | ✓ 60.10  |
| REAR EXHAUST ALUMINIUM HEAT SHIELD <i>Am Led</i>                 | 1   | 55.00      | ✓ 55.00  |
| REAR EXHAUST RUBBER MOUNTING <i>Am Led</i>                       | 2   | 16.50      | + 33.00  |
| REAR EXHAUST SILENCER BOX <i>Bent</i>                            | 1   | 517.70     | ✓ 517.70 |
| REAR EXHAUST SILENCER BOX GASKET <i>Am Led</i>                   | 1   | 48.30      | ✓ 48.30  |
| REAR FENDER ARCH GARNISH L/R <i>Deloid</i>                       | 2   | 195.00     | ✓ 390.00 |
| REAR FENDER INNER SHIELD L/R <i>Am Led</i>                       | 2   | 147.50     | + 295.00 |
| REAR FENDER INNER TRIM GARNISH L/R <i>Deloid</i>                 | 2   | 295.00     | ✓ 590.00 |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

AARON NG YEW KIAN  
 BLK 674B JURONG WEST ST 65 #09-60  
 SINGAPORE 642674

Contact : 85227756

## TAX INVOICE

Repair Code : CLM17370

Date in : 10/09/2022

Vehicle Num. : SMM7814A

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11116443/L15B4036447

|                                                          |   |        |                   |                   |
|----------------------------------------------------------|---|--------|-------------------|-------------------|
| REAR FLOOR JACK PANEL <i>Builed</i>                      | 1 | 95.00  | ✓                 | 95.00             |
| REAR FLOOR PANEL <i>Builed</i>                           | 1 | 662.20 | ✓                 | 662.20            |
| REAR FLOOR PANEL COMPARTMENT SPONGE TRAY <i>Relnd</i>    | 1 | 485.30 | <del>285</del>    | <del>485.30</del> |
| REAR FLOOR PANEL INNER TOP BOARD COVER <i>Relnd</i>      | 1 | 430.30 | <del>328</del>    | <del>430.30</del> |
| REAR TAILGATE <i>Distahd</i>                             | 1 | 953.30 | ✓                 | 953.30            |
| REAR TAILGATE 'VEZEL' EMBLEM <i>me</i>                   | 1 | 56.20  | ✓                 | 56.20             |
| REAR TAILGATE HINGES L/R <i>me</i>                       | 2 | 50.00  | +                 | 100.00            |
| REAR TAILGATE INNER PULL GARNISH <i>Relnd</i>            | 1 | 153.40 | ✓                 | 153.40            |
| REAR TAILGATE INNER TRIM GARNISH <i>Amhd</i>             | 1 | 180.00 | ✓                 | 180.00            |
| REAR TAILGATE MECHANISM LOCK <i>Amhd</i>                 | 1 | 180.00 | ✓                 | 180.00            |
| REAR TAILGATE MECHANISM LOCK STRIKER <i>me</i>           | 1 | 27.50  | +                 | 27.50             |
| REAR TAILGATE OUTER GARNISH <i>Amhd</i>                  | 1 | 220.00 | ✓                 | 220.00            |
| REAR TAILGATE OUTER GARNISH 'H' LOGO EMBLEM <i>me</i>    | 1 | 25.00  | ✓                 | 25.00             |
| REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R <i>me</i> | 2 | 38.50  | ✓                 | 77.00             |
| REAR TAILGATE REFLECTOR L/R <i>KA Amhd</i>               | 2 | 413.20 | <del>413.20</del> | <del>826.40</del> |
| REAR TAILGATE RUBBER GUIDE STOPPER L/R <i>me</i>         | 2 | 18.50  | +                 | 37.00             |
| REAR TAILGATE WEATHER STRIP <i>ht</i>                    | 1 | 96.80  | ✓                 | 96.80             |
| REAR TAILGATE WINDSCREEN INNER SEAL <i>me</i>            | 2 | 50.00  | ✓                 | 100.00            |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200616038C  
GST Registration No. : 200616038C

AARON NG YEW KIAN  
BLK 674B JURONG WEST ST 65 #09-60  
SINGAPORE 642674

Contact : 85227756

## TAX INVOICE

Repair Code : CLM17370

Date in : 10/09/2022

Vehicle Num. : SMM7814A

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11116443/L15B4036447

|                                                |         |   |         |           |
|------------------------------------------------|---------|---|---------|-----------|
| REAR TAILGATE WINDSCREEN MOULDING              | 8251.50 | 2 | 50.00   | 100.00    |
| REAR TAILLAMP L/R                              | 6601.20 | 2 | 474.60  | 474.60    |
| Subtotal before discount                       |         |   |         | 10,654.40 |
| Percentage discount 20%                        |         |   |         | 2,130.88  |
| Sub-total 1                                    |         |   |         | 8,523.52  |
| REAR BUMPER CLIPS - SET                        |         | 1 | 50.00   | 50.00     |
| REAR BUMPER REVERSE SENSOR                     |         | 1 | 280.00  | 280.00    |
| REAR BUMPER TOP CHROME PLATE                   |         | 1 | 300.00  | 300.00    |
| REAR FENDER ARCH GARNISH CLIPS L/R - SET       |         | 2 | 30.00   | 60.00     |
| REAR FENDER INNER SHIELD CLIPS L/R - SET       |         | 2 | 50.00   | 100.00    |
| REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET |         | 2 | 30.00   | 60.00     |
| REAR FLOOR PANEL INSULATOR MAT                 |         | 1 | 300.00  | 300.00    |
| REAR NUMBER PLATE                              |         | 1 | 25.00   | 25.00     |
| REAR NUMBER PLATE HOLDER                       |         | 1 | 50.00   | 50.00     |
| REAR TAILGATE AUTO DAMPER - SET                |         | 1 | 1800.00 | 1,800.00  |
| REAR TAILGATE INNER TRIM GARNISH CLIPS - SET   |         | 1 | 60.00   | 60.00     |
| REAR TAILGATE OUTER GARNISH CLIPS - SET        |         | 1 | 40.00   | 40.00     |
| REAR TAILGATE REVERSE CAMERA                   |         | 1 | 800.00  | 800.00    |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200616038C  
GST Registration No. : 200616038C

AARON NG YEW KIAN  
BLK 674B JURONG WEST ST 65 #09-60  
SINGAPORE 642674

Contact : 85227756

## TAX INVOICE

Repair Code : CLM17370

Date in : 10/09/2022

Vehicle Num. : SMM7814A

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11116443/L15B4036447

|                                   |   |       |    |           |
|-----------------------------------|---|-------|----|-----------|
| REAR TAILGATE SPOILER CLIPS - SET | 1 | 50.00 | 20 | 50.00     |
| REAR TAILGATE WINDSCREEN SEALANT  | 1 | 60.00 | ✓  | 60.00     |
| REAR TAILLAMP CLIPS L/R - SET     | 2 | 30.00 | 20 | 60.00     |
| Subtotal before discount          |   |       |    | 4,095.00  |
| Percentage discount 0%            |   |       |    | 0.00      |
| Sub-total 2                       |   |       |    | 4,095.00  |
| Parts-total                       |   |       |    | 12,618.52 |

## LABOUR

- To reset system after repair works
- To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.
- To remove, reinstall tailgate windscreen
- To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.
- To remove, reinstall tailgate mechanism and check for function

Labour Total

Parts & Labour Total

3,710.00

16,328.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is a computer-generated document which requires no signature.\*\*\*

page 4

Aaron L  
H/S 14/09/22

08 Days

total: 9841.20

L/S: 7.8K ✓