



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2300354

INV Date 17/01/2023

Reference CC4/LPC22009056/Tpa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. PD 3677S
Insured Veh. XE 6850M
Claim No. 21/22/22/VC00/026290
Policy No. Z/21/VC00/112819
Accident Date 12/09/2022
Inspection Date 16/09/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC22009056/Tpa3q2 Date: 17/01/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 6850M		Veh. Inspected	PD 3677S
Policy No.	Z/21/VC00/112819		Coverage (\$)	0.00
Claim No.	21/22/22/VC00/026290		Excess (\$)	0.00
Assign From	ENG HUEY NI		Assign Date	14/09/2022
2. Vehicle Particulars & Condition				
Make & Model	FTBCI LEXBUILD HOLA		c.c	7475
Engine No.	HIDDEN		Year of Reg.	2021
Chassis No.	LA9L1GAJ9KFFBC183		Colour	PURPLE
Odometer	69344 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	NIL
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre	11 R22.5		DUNLOP	8 mm
L/H Front Tyre	11 R22.5		DUNLOP	8 mm
R/H Rear Tyre	11 R22.5 (D)		DUNLOP	8/8 mm
L/H Rear Tyre	11 R22.5 (D)		DUNLOP	8/8 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/09/2022		Inspection Date	16/09/2022
Survey held at	LEXBUILD INTERNATIONAL PTE LTD 2 WOODLANDS SECTOR 1 ,#05-12 (WOODLANDS SPECTRUM 1) SINGAPORE 738068			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PD 3677S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR CAR PLATE	CRACKED	100.00	30.00
1	REAR FOG LAMP	CUT	300.00	150.00
1	60KM/H STICKER	NECESSARY	80.00	40.00
1	LEXBUILD LOGO	NECESSARY	100.00	80.00
			580.00	300.00
	<u>LABOUR</u>			
	SUPPLY SKILLED LABOUR TO:REPLACE REAR CAR PLATE ,REPAIR REAR ENGINE PANEL ASSEMBLY.		4,400.00	880.00
	SUPPLY SKILLED ELECTRICIAN TO REPLACE: REAR FOG LAMP.		100.00	40.00
	SUPPLY SKILLED PAINTER & PAINT MATERIAL TO PUTTY ,GRINDING & SPRAYPAINT:REAR ENGINE PANEL,REAR MIDDLE BUMPER ,REAR LHS/RHS LOWER DOME.		2,640.00	1,320.00
			7,140.00	2,240.00
GRAND TOTAL			7,720.00	2,540.00
RECOMMENDED COST OF REPAIRS				2,540.00

Report Ref No. CC4/LPC22009056/Tpa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. PD 3677S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. PD 3677S

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

