

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/III22009057/RNY3E2**Date:** 09/03/2023REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549_02
Claimant Vehicle No :	FU1111A	Insured Vehicle No :	GBK8763Y
Date of Loss:	10/09/2022	Nature of Claim:	TP
		Claim No:	MFL2022D0007132

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FU1111A	Engine No:	G3L8E0606190
Make & Model:	YAMAHA NMAX155, 155cc ABS CVT	Chassis No:	MH3SG5680MK086264
Reg. Date:	02/07/2021 (Man. Year: 2021)	Odometer:	47002 km
Colour:	Black		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70-13	Rear Tyre Size:	140/80-13
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,444.10	2,443.20	4,000.90	62.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	790.00	270.00	520.00	65.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,234.10	2,713.20	4,520.90	62.49
Approved Total (Overridden) (S\$)		2,150.00		
	(S\$)	7,234.10	2,150.00	5,084.10
	+ GST 8.00/8.00% (S\$)	578.73	172.00	406.73
	Nett Amount (S\$)	7,812.83	2,322.00	5,490.83

INSPECTION

Date of Assignment:	14/09/2022	
Date Inspected:	19/09/2022	Inspected At: KM PLUS MOTOR PTE LTD (HQ) 61 WOODLANDS IND PARK E9, #01-14 E9 PREMIUM Singapore 757047
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 09 Mar 2023)	
Parts:	N/A	YAMAHA NMAX155 155cc ABS CVT (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FU1111A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE FORK TUBE ASSY	Repair	980.00 FL	*- FL
2	1		*FORK UNDER BRACKET	Intact	190.00 FL	*- FL
3	1		*FRONT SPORT RIM	Repair	650.00 FL	*- FL
4	1		*HEADLAMP	Damaged	800.00 FL	*550.00 FL
5	1		*N/S SIDE MIRROR	Damaged	120.00 FL	*65.00 FL
6	1		*HANDLE BAR	Damaged	180.00 FL	*148.00 FL
7	1		*N/S HANDLE BAR BALANCER	Damaged	60.00 FL	*60.00 FL
8	1		*CLUTCH LEVER	Damaged	58.00 FL	*52.00 FL
9	1		*LOWER BELLY PANEL	Damaged	250.00 FL	*250.00 FL
10	1		*SET REAR PASSENGER HANDLE	Repair	190.00 FL	*- FL
11	1		*REAR TAILLAMP	Not Necessary	285.00 FL	*- FL
12	1		*ENGINE COVER	Damaged	350.00 FL	*295.00 FL
13	1		*AIR FILTER BOX COVER	Not Necessary	220.00 FL	*- FL
14	1		*MAIN STAND	Not Necessary	145.00 FL	*- FL
15	1		*SIDE STAND	Not Necessary	95.00 FL	*- FL
16	1		*REAR FENDER	Damaged	148.00 FL	*148.00 FL
17	1		*HORN	Not Necessary	158.00 FL	*- FL
18	1		*SET FAIRING COVER	Damaged	1,350.00 FL	*980.00 FL
19	1		*REAR NUMBER PLATE	Not Necessary	18.00 FS	*- FS
20	1		*REAR BOX BRACKET	Damaged	250.00 FS	*150.00 FS
21	1		*SET STEERING CONE	Not Necessary	120.00 FS	*- FS
22	1		*REAR CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,067.00	2,698.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	622.90	254.80
Total Parts (\$\$)	6,444.10	2,443.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE	New	50.00	0.00
2	TO REMOVE, REFIT AND STRAIGHTEN FRONT FORK TUBES	New	180.00	0.00
3	TO CHECK ELECTRICAL SYSTEM, WIRE HARNESS AND FOCUS HEADLAMP	New	80.00	20.00
4	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT	New	480.00	250.00
			Gross Labour Cost (\$\$)	790.00
				270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >