



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 7459G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR DOOR RH	TO REPAIR SEE LABOUR	1,309.00	-
1	REAR DOOR FAME STICKER 1	NOT NECESSARY	25.00	-
1	REAR DOOR FAME STICKER 2	NOT NECESSARY	25.00	-
	LESS 20% DISCOUNT		-271.80	-
			1,087.20	-
	<b><u>LABOUR</u></b>			
	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS. INCLUSIVE OF THE REPAIR OF REAR DOOR RH.		450.00	250.00
	SPRAYPAINTING CHARGES.		520.00	400.00
			970.00	650.00
<b>GRAND TOTAL</b>			<b>2,057.20</b>	<b>650.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>650.00</b>

Report Ref No. CS/SPF22009060/Svy3m4

**NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$650-\$750**

**S MOHAMED IRFAN BIN MOHAMED IQUBAL**

Asst. Automotive Assessor

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.