



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2301641

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 17/03/2023
Reference CC6/CTI22009061/Gpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SNF 7577J
Insured Veh. SKQ 7778Z
Claim No. SNM22D206583/C02
Policy No. DMPCSNA00183902107
Accident Date 14/09/2022
Inspection Date 16/09/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22009061/Gpa3q2 Date: 17/03/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKQ 7778Z	Veh. Inspected	SNF 7577J
	Policy No.	DMPCSNA00183902107	Coverage (\$)	0.00
	Claim No.	SNM22D206583/C02	Excess (\$)	0.00
	Assign From		Assign Date	14/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	TESLA MODEL 3 PERFORMANCE	c.c	0
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	LRW3F7EL2MC282991	Colour	WHITE
	Odometer	14794 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/35 R20	PIRELLI	6 mm
	L/H Front Tyre	235/35 R20	PIRELLI	6 mm
	R/H Rear Tyre	235/35 R20	PIRELLI	6 mm
	L/H Rear Tyre	235/35 R20	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	14/09/2022	Inspection Date	16/09/2022
	Survey held at	OPTIMA WERKZ PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #01-05 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNF 7577J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOTLID	BENT	728.97	728.97
1	REAR BOOTLID 'TESLA' EMBLEM	NECESSARY	37.38	37.38
1	REAR BOOTLID WEATHERSTRIP	NOT NECESSARY	121.50	-
1	REAR BOOTLID LOCK	CUT	54.21	54.21
1	REAR BOOTLID INNER TRIM BOARD	NOT NECESSARY	46.73	-
1	REAR BUMPER	DEFORMED	631.00	631.00
1	REAR BUMPER CENTER BRACKET	BROKEN	52.34	52.34
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	271.03	-
1	REAR BUMPER LOWER LIP	CUT	140.19	140.19
2	REAR BUMPER PARKING SENSOR @\$163.55	NOT WORKING (1 PCS ONLY)	327.10	163.55
2	REAR BUMPER PARKING SENSOR BRACKET @\$4.67	NECESSARY (1 PCS ONLY)	9.34	4.67
1	REAR END PANEL	TO REPAIR SEE LABOUR	448.60	-
1	REAR END PANEL UPPER COVER	NOT NECESSARY	23.36	-
	LESS 10% DISCOUNT		-289.18	-181.23
			2,602.57	1,631.08
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER CLIPS (SN)	NECESSARY	60.00	60.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	100.00	-
1	REAR NUMBER PLATE HOLDER (SN)	CRACKED	30.00	30.00
1	REAR END PANEL JOINT SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR END PANEL UPPER COVER CLIPS (SN)	NOT NECESSARY	50.00	-
			320.00	90.00
<u>LABOUR</u>				
	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST REAR ACCIDENT AREAS & ETC.INCLUSIVE OF THE REPAIR OF REAR END PANEL .		800.00	400.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOTLID ,REAR BUMPER ,REAR END PANEL & ETC.		800.00	600.00

Report Ref No. CC6/CTI22009061/Gpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR CHARGES TO REMOVE & REINSTALLED REAR BOOTLID INNER TRIM MECHANISM & ETC .TO EFFECT REPLACE OF REAR BOOTLID.		150.00	60.00
	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER PARKING SENSOR & ETC.		150.00	40.00
	TO DIAGNOSIS FAULT CODE & RESET MEMORY.	NOT NECESSARY	150.00	-
	TO CHECK WIRING & ELECTRICAL SYSTEM.	NOT NECESSARY	80.00	-
			2,130.00	1,100.00
GRAND TOTAL			5,052.57	2,821.08
RECOMMENDED COST OF REPAIRS				2,821.08

Report Ref No. CC6/CTI22009061/Gpa3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNF 7577J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNF 7577J

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNF 7577J

RE-INSPECTION

