

Date: 14/09/2022
Vehicle No: SNF7577J
Model: TESLA MODEL 3 PERFORMANCE
Chassis: LRW3F7EL2MC282991-2021
Reg.Year: 2021

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SKQ7778Z
Date of Accident: 14/09/2022
Estimator: TING AN
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BOOTLID / HT	1		\$728.97
2	REAR BOOTLID "TESLA" EMBLEM / RL.	1		\$37.38
3	REAR BOOTLID WEATHERSTRIP X NN	1		\$121.50
4	REAR BOOTLID LOCK ?	1		\$54.21
5	REAR BOOTLID INNER TRIM BOARD X NN	1		\$46.73
6	REAR BUMPER / RL	1		\$631.00
7	REAR BUMPER CENTER BRACKET ?	1		\$52.34
8	REAR BUMPER REINFORCEMENT ?	1		\$271.03
9	REAR BUMPER LOWER LIP / RL	1		\$140.19
10	REAR BUMPER PARKING SENSOR ?	2	\$163.55	\$327.10
11	REAR BUMPER PARKING SENSOR BRACKET ?	2	\$4.67	\$9.34
12	REAR END PANEL X RL	1		\$448.60
13	REAR END PANEL UPPER COVER ?	1		\$23.36
SUB TOTAL				\$2,891.75
LESS 10%				-\$289.18
PARTS TOTAL				\$2,602.58

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS / RL.	1		\$60.00
2	REAR NUMBER PLATE X NN	1		\$100.00
3	REAR NUMBER PLATE HOLDER / RL	1		\$30.00
4	REAR END PANEL JOINT SEALANT X NN	1		\$80.00
5	REAR END PANEL UPPER COVER CLIPS ?	1		\$50.00
S/N TOTAL				\$320.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

\$800.00 400

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOTLID, REAR BUMPER, REAR END PANEL & ETC.

\$800.00 600

LABOUR CHARGES TO REMOVE & REINSTALLED REAR BOOTLID INNER TRIM MECHANISM & ETC. TO EFFECT REPLACE OF REAR BOOTLID.

\$150.00 60

Head office

6 Kung Chong Road Singapore 159143
Tel (+65) 6472 1313 | Fax (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel (+65) 6484 9919 | Fax (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047
Tel (+65) 6481 1522 | Fax (+65) 6481 1011



Date: 14/09/2022
Vehicle No: SNF7577J
Model: TESLA MODEL 3 PERFORMANCE
Chassis: LRW3F7EL2MC282991-2021
Reg.Year: 2021

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SKQ7778Z
Date of Accident: 14/09/2022
Estimator: TING AN
Surveyor:

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER PARKING SENSOR & ETC.	\$150.00	40
TO DIAGNOSIS FAULT CODE & RESET MEMORY. (photo)	\$150.00	?
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$80.00	X
LABOUR TOTAL		\$2,130.00

TING AN

TOTAL

\$5,052.58

4 Days.
part by mt.
before part photo.
Gue Qianf
8288 0282
16/9/2022.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

8 Kung Chong Road Singapore 150143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 0919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

