

ASS. REC. BY:

REF:

CTZ/ 22009063/Kc

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

1.81 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 9893P

Yr Regn:

12, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

c.c.

1798

Colour

mp. white / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

106909

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU403093263

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Wastl

195/65R15

Navigator

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

6

mm

L/Bal.

8

mm

L/Bal.

6

mm

D.O.A.

13/9/22

D.O.I.

14/9/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/3 @ 6038.40 Cont

Date/Time, File Pass to?



: Prel. Report

1)

Date/Time, File Return to?



: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Fines

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9893P

Not Notified
 Penny Bepain AAD2209-
 @ 6038.40

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

14 SEP 2022

SHD9893P

JTDKB3FU403093263

TOYOTA

PRIUS GEN 4

13/09/2022

SLL6856C/ China

30/12/2020

PART**LIST**

1	PANEL SUB-ASSY, FRONT DOOR, RH	\$	B 1,300.70	✓
1	LOCK ASSY, FRONT DOOR W/MOTOR, RH	\$	R 603.20	X
1	MOULDING, FRONT DOOR WINDOW FRAME, FRONT RH	\$	Sm 38.60	X
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$	Sm 193.50	✓
1	HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$	md 390.60	✓
1	MOTOR ASSY, POWER WINDOW REGULATOR, RH	\$	Sm 926.00	X
1	WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	\$	Sm 321.10	X
1	HINGE ASSY, FRONT DOOR, LOWER RH	\$	R 110.60	X
1	HINGE ASSY, FRONT DOOR, UPPER RH	\$	R 97.50	X
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$	Sm 238.30	X
1	TAPE, BLACK OUT, NO.2 FRT RH	\$	Sm 43.50	✓
1	TAPE, BLACK OUT, NO.1 FRT RH	\$	Sm 13.30	✓
1	TAPE, BLACK OUT, NO.3 FRT RH	\$	Sm 26.30	✓
1	PANEL SUB-ASSY, REAR DOOR, RH	\$	R 1,294.90	✓
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$	Sm 193.50	X
1	HANDLE ASSY, REAR DOOR OUTSIDE, RH	\$	Sm 97.40	X
1	WEATHERSTRIP, REAR DOOR OPENING TRIM, RH	\$	Sm 293.00	X
1	MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH	\$	Sm 926.00	X
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$	Sm 206.70	X
1	TAPE, BLACK OUT, NO.2 REAR RH	\$	mc 34.90	✓
1	TAPE, BLACK OUT, NO.3 REAR RH	\$	Sm 15.40	✓
1	TAPE, BLACK OUT, NO.1 REAR RH	\$	Sm 21.90	✓
1	HINGE ASSY, REAR DOOR, LOWER RH	\$	R 87.10	X
1	HINGE ASSY, REAR DOOR, UPPER RH	\$	R 98.90	X
1	PANEL SUB-ASSY, QUARTER, RH	\$	R 871.50	X

Trans-cab Auto Services Pte Ltd**AAD2209-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9893P

1 LINER, REAR WHEEL HOUSE, RH	\$	<i>Pm</i> 139.80	X
1 MOULDING ASSY, BODY ROCKER PANEL, RH	\$	<i>CR1</i> 594.80	<i>✓</i>
1 MIRROR ASSY, OUTER REAR VIEW, RH	\$	<i>Pm</i> 1,436.60	X
1 FENDER SUB-ASSY, FRONT RH	\$	<i>Rm</i> 977.80	<i>✓</i>
1 LINER, FRONT FENDER, RH	\$	<i>Dir</i> 202.50	<i>✓</i>
1 EMBLEM, SIDE PANEL, RH	\$	<i>Mc</i> 54.60	<i>✓</i>
1 HUB CAP	\$	<i>NIP</i> 211.50	X
1 HUB CAP	\$	<i>NIP</i> 211.50	X
1 RIM	\$	<i>Pm</i> 1,900.10	X
1 RIM	\$	<i>Pm</i> 1,900.10	X
1 BRACKET, FRONT BUMPER SIDE, RH	\$	<i>Sm</i> 59.30	X
1 SUPPORT, FRONT BUMPER SIDE, RH	\$	<i>Sm</i> 80.10	X
1 RETAINER, REAR BUMPER SIDE, RH	\$	<i>Sm</i> 132.60	X
1 COVER, FRONT BUMPER	\$	<i>Al</i> 521.00	X
1 COVER, REAR BUMPER	\$	<i>Al</i> 485.60	X
TOTAL	\$	17,352.30	
25%	\$	4,338.08	
	\$	13,014.23	

Special Nett

2 FENDER LINER CLIP	\$	<i>nn</i> 130.00	X
1 REAR BUMPER CLIP	\$	<i>nn</i> 65.00	X
1 FRT BUMPER CLIP	\$	<i>nn</i> 65.00	X
1 DOOR STICKER TRANSCAB	\$	<i>nn</i> 100.00	<i>GOJA</i>
1 DOOR STICKER TEL. NO	\$	<i>nn</i> 100.00	<i>GOJA</i>
2 DOOR TRIM CLIP	\$	<i>nn</i> 150.00	X
2 DOOR WEATHERSTRIP CLIP	\$	<i>nn</i> 160.00	X
TOTAL	\$	770.00	
TOTAL PARTS	\$	13,784.23	

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas. \$ 240.00 *Pol*

Trans-cab Auto Services Pte Ltd**AAD2209-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9893P

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 *601*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,600.00 *7001*

To transfer of rear end panel fittings, attachment to facilitate bodywork repair.

\$ *nn* 380.00 *X*

Putty And Spray Painting Of The Affected Portion.

\$ 1,600.00 *13201*

To reinstall rear bumper parking sensor.

\$ *nn* 170.00 *X*

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 *X*

To Check Electrical Lighting Concerned.

\$ 170.00 *201*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 *X*

To remove and refit of rear fender fittings, attachment and perform water seepage test.

\$ *nn* 170.00 *X***TOTAL \$ 5,100.00****Over All Total \$ 18,884.23****(PART-BY-PART) Repair Days***20 Days**6 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: