

# PERFECT AUTOMOBILE APPRAISAL SERVICES

10 Hougang Street 11 #14-29 The Minton Singapore 534080

Hand phone No. 96683949

Company Registration No. 53103119E

## THIRD PARTY CLAIM

To : Swee Bee Contractor Pte Ltd  
c/o : 160 Sin Ming Drive  
#06-06 Sin Ming Autocity  
Singapore 575722

Date : 4th July 2022

Our Ref : PA/MI/22/1014/1

### REFERENCE :

ASSIGNED BY : Owner  
ASSIGNED ON : 25th May 2022  
  
WORKSHOP : Omega Auto Pte Ltd  
160 Sin Ming Drive  
#06-06 Sin Ming Autocity  
Singapore 575722  
  
ACCIDENT DATE : 19th May 2022  
SURVEY DATE : 25th May 2022

### VEHICLE DETAILS :

REGN PLATE	: XE 2548 M	COLOUR	: Yellow
MAKE & MODEL	: Nissan UD Trucks	GEN BODY WORK	: Good
YEAR REGN	: 2017	AUDIO PLAYER	: Yes
ENG CAPACITY	: 10837cc	AIR CONDITIONER	: Yes
ENGINE NO.	: GH11740053	STEERING	: Serviceable
CHASSIS NO	: JNCM1F1D5HU015241	HAND BRAKE	: Serviceable
MILEAGE	: 210600Km	FOOT BRAKE	: Serviceable

### TYRES SIZE & CONDITION :

FRONT O/S : Falken 295/80 R 22.5 approximately 50%  
FRONT N/S : Falken 295/80 R 22.5 approximately 50%  
REAR O/S : Westlake 295/80 R 22.5 approximately 60%  
REAR N/S : Westlake 295/80 R 22.5 approximately 60%

Note : The above percentage represent the remaining estimated life of the tyre treads.

Our Ref : PA/MI/22/1014/1

Veh. No. : XE 2548 M

**GENERAL DESCRIPTION OF DAMAGES :**

At the time of inspection, we noted that this vehicle sustained damages at the rear LH body of the vehicle.

For more details of the damages, please see schedule and photographs attached.

Attached twenty-four (24) photographs taken during our inspections.

**CONCLUSIONS & RECOMMENDATIONS :**

ORIGINAL QUOTATION : \$ 2,480.00

REVISED QUOTATION : \$ 1,700.00 (Lump Sum)

We have thoroughly inspected each and every item on the estimate against the physical damages found on the vehicle. We have listed the breakdown of our findings and our recommendations as per assessment attached.

In normal circumstances, the repairs would take approximately two (2) days to complete.

In accordance to your instruction, we have **NOT AUTHORISED** repair to the vehicle and the survey was conducted strictly on a '**WITHOUT PREJUDICE**' basis. We hope that this report will be of assistance to you in dealing with this matter.

Should you discover any discrepancy in this report, please kindly notify us within two (2) weeks or this report will be treated as valid.

The information contained in these documents is privileged and confidential and is for the exclusive use of the addressee's designation. If you are not the addressee, any enclosure, reproduction, distributions or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for its return.

# PERFECT AUTOMOBILE APPRAISAL SERVICES

W/s Omega Auto Pte Ltd  
160 Sin Ming Drive  
#06-06 Sin Ming Autocity  
Singapore 575722

Our Ref : PA/MI/22/1014/1

Veh. No. : XE 2548 M

QTY	DESCRIPTIONS	COMMENTS/ CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
-----	--------------	------------------------	-----------------------	----------------------

## LIST PARTS

1 pc	Rear LH mudguard	dented	<i>R</i> \$ 850.00	\$ 850.00 <i>X</i>
1 pc	Rear LH step bracket	dented/ bent	<i>R</i> \$ 350.00	\$ 350.00 <i>X</i>
			\$ 1,200.00	\$ 1,200.00
		Less 10%	\$ 120.00	\$ 120.00
			\$ 1,080.00	\$ 1,080.00

## LABOUR CHARGES

To remove and repair rear LH side member  
including panel beating on affected areas.

\$ 1,000.00 \$ 700.00 *200d*


To putty and spray painting on rear damaged  
portion including touch up paint on accident  
affected areas.

\$ 300.00 \$ 180.00 ✓

To apply rustproofing, reseal tuff-coating  
treatment to rear replaced/ repaired parts  
and panels.

*nn* \$ 100.00 \$ 50.00 *X*  
\$ 2,480.00 \$ 2,010.00

The repairer has agreed to undertake repairs on a contractual basis at **Lump Sum**  
**\$ 1,700.00** corresponding to supply of parts, labour and spray painting charges.

  
**CHUAH POH SIONG GARY**  
**CAE, MIMI, AMSOE,**  
**AMIRTE, AMSAE-AUS, MSAAA**

*1 day*