

# SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM\_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No: 53231488C

09/09/2022

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

Accident dat : 08/09/2022

TP AXA.

Xiao Tong.

Estimated repair cost for vehicle no: SDD228S MERCEDES BENZ C200 AMG LINE (R18 LED)

CHASSIS: WDD2050422R062954 (2015)

| S/N | Qty | Items                                   | U/price    | Amount                 |
|-----|-----|-----------------------------------------|------------|------------------------|
| 1   | 1   | REAR BUMPER                             | \$1,651.30 | \$1,651.30 +           |
| 2   | 1   | LH REAR BUMPER SIDE BRACKET             | \$128.10   | \$128.10 +             |
| 3   | 1   | LH REAR BUMPER SIDE RETAINER            | \$1,456.70 | \$1,456.70 +           |
| 4   | 1   | LH REAR BUMPER SENSOR                   | \$354.60   | \$354.60 +             |
| 5   | 1   | LH REAR FENDER                          | \$2,544.10 | \$2,544.10 +           |
| 6   | 1   | LH REAR DOOR <i>Dented</i>              | \$3,697.50 | <u>\$3,697.50</u> 250  |
| 7   | 2   | LH REAR DOOR HINGE <i>3M</i>            | \$155.70   | \$311.40 +             |
| 8   | 1   | LH REAR DOOR CHECKER <i>3M</i>          | \$124.60   | \$124.60 +             |
| 9   | 1   | LH REAR DOOR WEATHER STRIPE <i>per</i>  | \$512.20   | <u>\$512.20</u> 28     |
| 10  | 1   | LH FRONT DOOR <i>Dented</i>             | \$3,697.50 | <u>\$3,697.50</u> 2190 |
| 11  | 2   | LH FRONT DOOR HINGE <i>3M</i>           | \$155.70   | \$311.40 +             |
| 12  | 1   | LH FRONT DOOR CHECKER <i>3M</i>         | \$124.60   | \$124.60 +             |
| 13  | 1   | LH FRONT DOOR WEATHER STRIPE <i>per</i> | \$512.20   | <u>\$512.20</u> 285    |
| 14  | 1   | FRONT BUMPER <i>3M</i>                  | \$1,985.30 | \$1,985.30 +           |
| 15  | 1   | LH FRONT BUMPER SIDE RETAINER <i>3M</i> | \$128.40   | \$128.40 +             |
| 16  | 1   | LH FRONT BUMPER SENSOR                  | \$321.00   | \$321.00 +             |
| 17  | 1   | LH FRONT FENDER <i>Dented</i>           | \$1,851.30 | <u>\$1,851.30</u> 1085 |
| 18  | 1   | LH FRONT LOWER ARM                      | \$874.30   | \$874.30 +             |
| 19  | 1   | LH FRONT UPPER ARM                      | \$846.60   | \$846.60 +             |
| 20  | 1   | LH FRONT SHOCK ABSORBER                 | \$1,522.30 | \$1,522.30 +           |
| 21  | 1   | LH FRONT KNUCKLER ARM                   | \$1,239.70 | \$1,239.70 +           |
| 22  | 1   | LH FRONT KNUCKLER ARM BEARING           | \$642.90   | \$642.90 +             |
| 23  | 1   | LH REAR LOWER ARM                       | \$562.30   | \$562.30 +             |
| 24  | 1   | LH REAR SHOCK ABSORBER                  | \$689.60   | \$689.60 +             |
| 25  | 1   | LH REAR UPPER ARM                       | \$384.70   | \$384.70 +             |
| 26  | 1   | LH REAR KNUCKLER ARM                    | \$746.90   | \$746.90 +             |
| 27  | 1   | LH REAR KNUCKLER ARM BEARING            | \$304.80   | \$304.80 +             |
| 28  | 1   | LH REAR ADJUSTER ARM                    | \$286.40   | \$286.40 +             |
| 29  | 1   | REAR WINDSCREEN GLASS MOULDING          | \$284.70   | \$284.70 +             |

*2005 Glass Regulator Gear*



SDD228S MERCEDES BENX C200 AMG

6288

5659.20

TOTAL : \$28,097.40  
LESS 10 % \$2,809.74  
SUB-TOTAL : \$25,287.66

| S/N | Qty | ITEMS / SPECIAL NETT | U/price    | Amount              |
|-----|-----|----------------------|------------|---------------------|
| 1   | 1   | REAR BUMPER CLIPS    | \$80.00    | \$80.00 <i>x</i>    |
| 2   | 1   | FRONT BUMPER CLIPS   | \$80.00    | \$80.00 <i>x</i>    |
| 3   | 1   | LH FRONT SPORT RIM   | \$2,200.00 | \$2,200.00 <i>x</i> |
| 4   | 1   | LH REAR SPORT RIM    | \$2,200.00 | \$2,200.00 <i>x</i> |
| 5   | 1   | LH FRONT TYRE        | \$420.00   | \$420.00 <i>x</i>   |
| 6   | 1   | LH REAR TYRE         | \$420.00   | \$420.00 <i>x</i>   |

TOTAL: \$5,400.00

TOTAL PARTS : \$30,687.66

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 5 TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS
- 6 LABOUR FOR REMOVE & REFIX REAR WINDSCREEN GLASS
- 7 LABOUR FOR REMOVE & REFIX REAR ROOF LINING/UPHOLSTERY/ RIM BOARD
- 8 LABOUR FOR REMOVE & TRASNFER ALL RH DOORS FITTING
- 9 LABOUR FOR REMOVE & RENEW LH FRONT & REAR R UNDER CARRIAGE
- 10 TO CONDUCT WHEEL ALIGNMENT

*800*  
\$1,800.00  
*1850* *750* \$1,600.00  
*50* \$80.00  
*50* \$200.00  
*x* \$150.00  
*x* \$200.00  
*200* \$300.00  
*x* \$600.00  
*x* \$150.00

\$5,080.00

Total:- \$35,767.66

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Adrian Lj*  
*1/5 19/09/22*  
*Supplementary 05 Days*  
*355.50*  
*total: 7864.70*  
*W/S: 6.3K*

*6.3K*

# SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM\_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No : 53231488C

Blk 1 Kaki Bukit Ave 6

09/09/2022

# 01-43

Singapore 417883

Accident dat : 08/09/2022

Estimated repair cost for vehicle no: SDD228S MERCEDES BENZ C200 AMG LINE (R18 LED)

CHASSIS: WDD2050422R062954 (2015)

## SUPPLEMENTARY

| S/N | Qty | Items                                                 | U/price  | Amount                         |
|-----|-----|-------------------------------------------------------|----------|--------------------------------|
| 1   | 1   | LH FRONT DOOR POWER WINDOW REGULATOR GEAR <i>dyd.</i> | \$580.00 | <del>\$580.00</del> <i>395</i> |

TOTAL : \$580.00

LESS 10 % \$58.00

SUB-TOTAL : \$522.00

*395*  
*Supplementary : 355.50*