



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914			Ref: CS/AWA22009084/Kny3m4 Date: 19/10/2022 Code: AWA	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XE 1799L	Veh. Inspected	SLT 8485J
	Policy No.	BVFCB0007172215	Coverage (\$)	0.00
	Claim No.	NSV2200150/HLF	Excess (\$)	0.00
	Assign From	HEW LEE FONG	Assign Date	15/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	AUDI A3 TFSI (A)	c.c	999
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WAUZZZ8VXJ1019195	Colour	M.P.D. GREY
	Odometer	62921 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	MICHELIN	8 mm
	L/H Front Tyre	205/55 R16	MICHELIN	8 mm
	R/H Rear Tyre	205/55 R16	MICHELIN	8 mm
	L/H Rear Tyre	205/55 R16	MICHELIN	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/09/2022	Inspection Date	28/09/2022
	Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	