

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
·						
				Ref:	CS/AWA22009084/y3	
	(SINGAPORE BRA 60 ANSON ROAD		Date:	15/09/2022		
	MAPLETREE ANS SINGAPORE 0799					
	ONOAI ONE 079	717		Code:	AWA	
1.		Policy Particulars				
	Insured Veh.	XE 1799L	Veh. Inspected		SLT 8485J	
	Policy No.	BVFCSB0007172215	Coverage (\$)		0.00	
	Claim No.	NSV2200150/HLF	Excess (\$)		0.00	
	Assign From	HEW LEE FONG	Assign Date		15/09/2022	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	13/09/2022	Inspection Date)		
	Survey held at	CHENG HOE MOTOR PL				
		BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					