

TO : CTP MOTOR CLAIMS DEPTS
 VEHICLE NO : SMC2707L
 CHASSIS : JM6BN22A8J0206952
 DATE OF ACCIDENT : 13.09.2022

32	FRONT KNUCKLE ARM <i>engd</i>	1	\$ 598.60	\$ 598.60	<i>455</i>
33	FRONT STABILIZER BAR LINKAGE RH <i>new</i>	1	\$ 85.60	\$ 85.60	<i>+</i>
34	FRONT DRIVESHAFT RH <i>new</i>	1	\$ 948.50	\$ 948.50	<i>+</i>
35	FRONT SHOCK ABSORBER RH <i>new</i>	1	\$ 425.90	\$ 425.90	<i>+</i>
36	FRONT STEERING RACK AND PINION <i>new</i>	1	\$ 1,925.60	\$ 1,925.60	<i>+</i>
37	FRONT WHEEL HUB BEARING LH <i>engd</i>	1	\$ 548.20	\$ 548.20	<i>325</i>

8468.20
6774.56 S.N. 500

TOTAL PRICE	\$ 18,628.70
LESS 20%	\$ 3,725.74
SUB TOTAL PRICE	\$ 14,902.96

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
2	FRONT BUMPER CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
3	FRONT BUMPER TOP COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
4	FRONT BUMPER UNDER COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
5	FRONT GRILLE CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
6	FRONT RADIATOR SUPPORT PANEL <i>new</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
7	AIR CON CONDENSER SIDE GARNISH LH <i>new</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
8	FRONT FENDER COWLING CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>30</i>
9	FRONT WHEEL TYRE LH <i>new</i>	1	\$ 450.00	\$ 450.00	<i>+</i>
10	BRAKE OIL <i>new</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
TOTAL				\$ 840.00	

90

TO : CTP MOTOR CLAIMS DEPTS
 VEHICLE NO : SMC2707L
 CHASSIS : JM6BN22A8J0206952
 DATE OF ACCIDENT : 13.09.2022

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,600.00	500
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	400
3	Tuff Coat	\$ 250.00	40
4	WIRING CHECK ON HEADLAMP	\$ 120.00	+ 30
5	REFOCUS HEADLAMP BEAM	\$ 100.00	+
6	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 300.00	200
7	TO PRESS FRONT WHEEL BEARING	\$ 60.00	+
8	FOUR WHEEL ALIGNMNET	\$ 120.00	80
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

1250

TOTAL \$ 4,330.00

TOTAL PARTS COST : \$ 15,742.96
 TOTAL LABOUR COST : \$ 4,330.00
 TOTAL REPAIR COST : \$ 20,072.96

Adrian L
 4/s 14/09/22

05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

total: 8614.56

4/s: 6.81c