



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 6991

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/116, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading

Dealing in New/Used Cars, Hire Purchase & Insurance.



INSURER:

Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2001439724	Date of Loss:	10/09/2022
Vehicle Reg. No.:	SJN3879U	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	FOO FANG CHEE		
Make/Model:	HYUNDAI AVANTE, 1.6 HD DOHC ABS AIRBAG 2WD (A)	Vehicle Reg. Date:	13/02/2019
Vehicle Colour:	BLACK		
Engine No:	G4FC9U595891	Chassis No:	KMHDU41BR9U688304
Odometer:	166316 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

	Amount
COST OF CLAIMS	
Parts	8,645.50
Miscellaneous Items	0.00
Labour	2,730.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	11,375.50
+ GST 7.00% (\$)	796.29
Nett Amount (\$)	12,171.79

This claim is handled by: ONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Merimen e-Claims

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Sep 2022)
 Parts: 143 HYUNDAI AVANTE 1.6 HD DOHC ABS AIRBAG 2WD (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SJN3879U)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET / DD	0.00	0.00	*520.00 F
2	1		*FRONT BONNET OUTER RUBBER / TH	0.00	0.00	*95.00 F
3	1		*FRONT BONNET INSULATOR / CR4	0.00	0.00	*210.00 F
4	1		*FRONT BONNET INSULATOR CLIPS / MC	0	0.00	*40.00 FS 20 net
5	1		*FRONT BONNET HINGE LH / BT	0.00	0.00	*48.00 F
6	1		*FRONT BONNET HINGE RH / BT	0.00	0.00	*48.00 F
7	1		*FRONT BONNET LOCK / BT	0.00	0.00	*55.00 F
8	1		*FRONT BONNET CABLE / CUT	0.00	0.00	*40.00 F
9	1		*FRONT BONNET LOCK STAY PANEL / BR	0.00	0.00	*75.00 F
10	1		*FRONT SUPPORT PANEL / OR	0.00	0.00	*460.00 F
11	1		*FRONT AIR CLEANER DUCT / OR	0.00	0.00	*196.00 F
12	1		*FRONT AIR CLEANER HOSE / broken	0.00	0.00	*110.00 F
13	1		*FRONT GRILLE / BK	0.00	0.00	*180.00 F
14	1		*FRONT GRILLE EMBLEM / OR	0.00	0.00	*48.00 F
15	1		*FRONT GRILLE MOULDING / BR	0.00	0.00	*110.00 F
16	1		*FRONT GRILLE CLIPS / MC	0	0.00	*30.00 FS 20 net
17	1		*FRONT BUMPER / OR	0.00	0.00	*380.00 F
18	1		*FRONT BUMPER REINFORCEMENT / BT	0.00	0.00	*150.00 F
19	1		*FRONT BUMPER INNER SPONGE / OR	0.00	0.00	*95.00 F
20	1		*FRONT BUMPER SIDE RETAINER LH / OR	0.00	0.00	*30.00 F
21	1		*FRONT BUMPER SIDE RETAINER RH / OR	0.00	0.00	*30.00 F
22	1		*FRONT BUMPER LOWER GRILLE / PR	0.00	0.00	*62.00 F
23	1		*FRONT BUMPER FINISHER COVER RH / CR4	0.00	0.00	*46.00 F
24	1		*HEADLAMP LH / BK	0.00	0.00	*420.00 F
25	1		*HEADLAMP RH / BK	0.00	0.00	*420.00 F
26	1		*HORN / BT	0.00	0.00	*72.00 F
27	1		*WIPER TANK / OR	0.00	0.00	*80.00 F
28	1		*SPARE TANK (power steering oil tank) / CR4	0.00	0.00	*62.00 F
29	1		*RADIATOR / BT	0.00	0.00	*580.00 F
30	1		*RADIATOR FAN ASSY / OR (Part)	0.00	0.00	*560.00 F
31	1		*RADIATOR FAN GUARD / BR	0.00	0.00	*210.00 F
32	1		*RADIATOR COOLANT / MC	0	0.00	*50.00 FS 30 net
33	1		*AIR COND CONDENSOR / BT	0.00	0.00	*620.00 F
34	1		*AIR COND LIQUID TUBE / ? x nn	0.00	0.00	*175.00 F X
35	1		*AIR COND PRESSURE PIPE / ? x nn	0.00	0.00	*380.00 F X
36	1		*AIR COND COOLNIG PIPE / ? x nn	0.00	0.00	*158.00 F X
37	1		*INKLET MANIFOLD / ? x nn	0.00	0.00	*480.00 F X
38	1		*FRONT FENDER LH / BT	0.00	0.00	*250.00 F
39	1		*FRONT FENDER RH / OR	0.00	0.00	*250.00 F
40	1		*FRONT NUMBER PLATE	0	0.00	*250.00 F
41	1		*FRONT NUMBER PLATE HOLDER / OR	0	0.00	*30.00 FS net
42	1		*FRONT WHEEL HOUSE LH/RH (REPAIR) / X R	0.00	0.00	*20.00 FS net
43	1		*FRONT WHEEL HOUSE CHASIS LH/RH (REPAIR) / X R	0.00	0.00	-

F=Franchise part. S=SpcNett.

Sub Total (\$\$) 8,775.00
 + Margin on L,N Items 10.00% (\$\$) 770.50
 Total Parts (\$\$) 8,645.50

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

6512 120 net
 + 10%
 7163.20



Estimates on Miscellaneous Items
 There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE, REPLACE, REFIT RADIATOR, RADIATOR FAN ASSY, AIRCOND CONDENSER, AIR COND LIQUID TUBE, AIR COND PIPE & ETC.	New 80	120.00 ✓
2	TO CHECK WIRING & ELECTRICAL SYSTEM	New 30	80.00
3	TO HYDRAOLICALLY JACK & REALIGN FRONT BOTH CHASIS FRAME & ETC. BACK TO ORIGINAL OPERATIONS	New 250	280.00 ✓
4	TO REMOVE, REPLACE, REPAIR, READJUST FRONT ACIDENT AREAS SUCH AS FRONT BONNET, FRONT SUPPORT PANEL, FRONT BUMPER, FRONT WHEEL HOUSE L/R, FRONT WHEEL HOUSE CHASSIS L/R, FRONT FENDER L/R & ETC. BACK TO ORIGINAL CONDITIONS	New	850.00 ✓
5	TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT GRILLE, FRONT BUMPER, FRONT SUPPORT PANEL, FRONT WHEEL HOUSE L/R, FRONT FENDER L/R & ETC.	New 1200	1,300.00
6	TO REFILL AIR COND GAS & VACUUM	New	100.00 ✓
Gross Labour Cost (\$)			2,730.00

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve (LKK)
 16/9/22, 10.11a

OD- N/A AC
 Excess - ?

L/S
 My AFy by
 7 dys

2510
 = 9793.70
 L/S - 7834.56
 = 7850

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: