

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Faiz Rosli

Date: 12 May 2023

Preliminary Advice

Insured Vehicle No	: SKQ1732U	Accident Date	: 13/09/2022
TP Vehicle No	: SLT4442J	Assignment Date	: 15/09/2022
Make	: HONDA VEZEL	Est. Duration of Repair	: 7
Date of Inspection	: 15/09/2022		
Inspection At	: H C AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #05-09 SIN MING AUTO CITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,865.08
Revised Amount	:S\$	6,378.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,378.00
Lump Sum Repair	:S\$	5,100.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.