

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/198R GS1 Reg. No. 19-900/198-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	R	ef:	CS/AGI22009090/Avy3e2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	D	ate:	02/12/2022	
			С	ode:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLE 6054L	Veh. Inspected		GBJ 7058L	
	Policy No.	P10199093R03	Coverage (\$)		0.00	
	Claim No.	C10017284/CD	Excess (\$)		0.00	
	Assign From	SALIZAWATI HAIZAR	Assign Date		15/09/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA DYNA	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	JTFAT35Y50K213758	Colour		SILVER	
	Odometer	84317 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195 R15C	CONDOR		6 mm	
	L/H Front Tyre	195 R15C	CONDOR		6 mm	
	R/H Rear Tyre	155 R12C	TOURADOR		6 mm	
	L/H Rear Tyre	155 R12C	TOURADOR		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	02/09/2022	Inspection Date		15/09/2022	
	Survey held at	KT MOTORWERK				
		3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: