


ASS. REC. BY: MarcusREF: CC4/ASM 22009091/ue93**ASSIGNMENT**From: /Date: /Estimated Cost: /OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SKS 352Dat Workshop m/s RLof SHIA 1634PInsured: SHIA 1634PPolicy No. /Claims No. /Sum Insured: /Excess: /(Client's Record) /Make of Veh: /(Policy Condition) /

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 39k.IDAC Accident Rpt: /

Consistent? : Yes or No

GIA / PR Seen: /

Consistent? : Yes or No

Est. Repairs: 8

days

Res.: Yes or No

Lum Sum: 20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS 182JDate: /Person Contacted: L7A8 23150

Vehicle: IN / OUT

Date / Time

Action / Instruction

28/5/22 have under at folder with 815810
have GIA
4/5 @ 13.000 informed Alan.

Veh No: SKS 352DYr Regn: 23/03/15Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA /Make: Toyota corolla A/Tc.c 1598Colour: silverA/C: Insured / Std / NI / NASp. Reading: 162184T/Radio: Insured / Std / NI / NAEng/No: /C/No: MRO53REM 104 528574Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55-216R: /BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or /

Front

Rear

R/Bal. 7

mm

R/Bal. 7

mm

L/Bal. 7

mm

L/Bal. 7

mm

D.O.A. 14/09/22D.O.I. 15/09/22Survey held at /Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop orThe U/C / Chassis frame / Body Structure affected due to collision. Reer & RL.

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report
Days Of Repair: 7Resurvey No. of Trip: /Add Fee: ☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee: /Transportation: /) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

VEHICLE No: SKS 352D

Asher

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Asher

15/9/12

2/5 \$13,000 / 8 days

1PC	BOOTLID	Buc	922.10	\$966.10	✓
1PC	BOOTLID REAR LOGO	neu		\$68.50	✓
1PC	BOOTLID 'COROLLA' EMBLEM	neu		\$62.80	✓
1PC	BOOTLID 'ALTIS' EMBLEM	neu		\$58.00	✓
1PC	BOOTLID INNER LOCK	twi	382.00	\$409.10	✓
1PC	BOOTLID LOCK CABLE	one/jm		\$66.80	✓
1PC	BOOTLID WEATHERSTRIP	twi		\$282.30	✓
2PCS	BOOTLID REFLECTORS @\$310.90	11		\$621.80	X
1PC	BOOTLID INNER TRIM	11		\$366.10	X
1PC	BOOTLID OUTER CHROME GARNISH	11		\$311.80	X
2PCS	BOOTLID HINGES @\$165.00	11		\$330.00	X
1PC	REAR BUMPER	Dis	605.10	\$655.10	✓
1PC	REAR BUMPER BEAM	Dis		\$395.40	✓
2PCS	REAR BUMPER REFLECTORS @\$60.00	11		\$120.00	X
2PCS	REAR BUMPER SIDE RETAINERS @\$65.00	Surf		\$130.00	✓
1SET	REAR BUMPER CLIPS	neu		\$50.00	✓
1PC	REAR END PANEL	Body	590.00	\$788.20	✓
1PC	REAR END PANEL TOP GARNISH	twi	284.10	\$362.30	✓
2PCS	TAILLAMPS @\$680.00	one	485 x 2 = 970	\$1,360.00	✓
2PCS	TAILLAMP LOWER BRACKETS @\$65.00	one		\$130.00	✓
2PCS	TAILLAMP HOUSING PANELS @\$425.00	11		\$850.00	X
1PC	REAR ANTENNA SENSOR	11		\$241.20	X
1PC	REAR FLOOR PANEL	11		\$1,145.20	X
1PC	REAR FLOOR PANEL TOP BOARD	born	485.10	\$620.50	✓
1PC	REAR FLOOR PANEL SIDE O/S MEMBER	11		\$366.10	X
2PCS	REAR FENDERS @\$945.10	11		\$1,890.20	X
2PCS	REAR FENDER INNER TRIMS @\$281.10	11		\$562.20	X
1PC	REAR EXHAUST	11		\$899.10	X
1PC	REAR EXHAUST HEAT SHIELD	11		\$122.10	X
1PC	REAR EXHAUST MOUNTING	11		\$45.00	X
1PC	REAR SPARE TYRE LOCK NUT	11		\$55.10	X
1PC	BONNET	Surf/unequal	1322.40	\$1,426.10	✓
1PC	BONNET INNER RUBBER	11		\$45.00	X
2PCS	BONNET HINGES @\$115.00	11		\$230.00	X
1PC	BONNET INSULATOR	11		\$281.00	X
1PC	BONNET LOCK	twi		\$105.00	✓
1PC	FRONT BUMPER	Dis	606.20	\$681.10	✓
2PCS	FRONT BUMPER SIDE RETAINERS @\$45.00	Surf		\$90.00	✓
1PC	FRONT BUMPER CENTRE GRILLE	11		\$108.00	X
1PC	FRONT BUMPER BEAM	11		\$561.10	X
1PC	FRONT BUMPER SPONGE	born		\$140.10	✓
2PCS	FRONT BUMPER FOG LAMPS @\$361.00	one	252	\$722.00	✓

8467-9

	FRONT BUMPER FOG LAMP COVERS @\$105.00	Tw	\$210.00 ✓
	FRONT BUMPER CLIPS	neu	\$50.00 ✓
	FRONT GRILLE	neu	\$381.90 ✓
	FRONT GRILLE LOGO	neu	\$68.50 ✓
1CS	HEADLAMPS @\$1050.00	neu	\$2,100.00 ✓ 1610.20
1PC	FRONT BRACE PANEL	Buf/w	\$121.00 ✓
2PCS	FRONT FENDERS @\$761.00	R	\$1,522.00 X
2PCS	FRONT FENDER INNER SHIELDS @\$161.00	neu	\$322.00 X
2PCS	FRONT FENDER 'VVTI' EMBLEMS @\$58.00	neu	\$116.00 ✓
1PC	FRONT SUPPORT PANEL	Buf	\$1,160.00 ✓
1PC	FRONT SUPPORT PANEL TOP GARNISH	11	\$210.00 X
1SET	FRONT SUPPORT PANEL TOP GARNISH CLIPS	11	\$50.00 X
1PC	AIR CON CONDENSER	Buf/enu	\$1,813.10 ✓
1PC	AIR CON DISCHARGE HOSE	11	\$481.90 X
1PC	AIR CON SUCTION HOSE	11	\$455.10 X
1PC	AIR CON PIPE	11	\$211.00 X
1PC	AIR CLEANER BOX ASSY	11	\$650.00 X
1PC	RADIATOR	Buf/enu	\$2,101.10 ✓
1PC	RADIATOR FAN ASSY	11	\$850.00 X
			\$31,594.00

S.NETT ITEM

1PC	REAR WINDSCREEN SEALANT	11	\$50.00 X
1PC	REAR WINDSCREEN INNER SEAL	11	\$50.00 X
1SET	REAR BUMPER REVERSE SENSOR	Shut	\$280.00 200
1PC	REAR END PANEL SEALANT	neu	\$50.00 ✓
1SET	REAR FLOOR PANEL INSULATOR	11	\$250.00 X
1SET	REAR REVERSE CAMERA	11	\$380.00 X
1PC	REAR LICENCE PLATE	11	\$50.00 X
1PC	FRONT LICENCE PLATE	Buf	\$50.00 40

TO CHECK WIRING	\$50.00	30
TO DISMANTLE & REPLACED REVERSE SENSOR	\$80.00	50
TO DISMANTLE & REFIX REAR WINDSCREEN	11 \$120.00	X
TO DISMANTLE & REFIX REAR EXHAUST	\$100.00	60
TO DISMANTLE & REFIX FUEL TANK	11 \$100.00	X
TO DISMANTLE & REFIX BOOTLID MECHANISM	\$100.00	60
TO RESET & REPROGRAMME SYSTEM	11 \$100.00	X
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80
TO DISMANTLE & REFIX REAR UNDER CARRIAGE	11 \$360.00	X
TO CONDUCT WHEEL ALIGNMENT	11 \$100.00	X
TO REFILL AIR CON GAS	\$100.00	✓
TO SPRAY RUST PROOFING	\$200.00	120
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$2,500.00	1600
TO PUTTY & SPRAY PAINTING	\$2,800.00	1800
TOTAL	\$39,584.00	

16099.7
25%
12074.77 290 3900