

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jacqueline Tan

Date: 17 Oct 2022

Preliminary Advice

Insured : GBG2960E

Vehicle No

TP Vehicle : SMX6055Y
No

Accident Date : 06/09/2022

Make : BMW X1 SDRIVE18I

Assignment Date : 15/09/2022

Date of : 21/09/2022

Est. Duration of : 5
Repair

Inspection At : PERFORMANCE MOTORS LIMITED (ALEXANDRA)
303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE
CENTRE
SINGAPORE 159941

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 14,195.85

Revised Amount :S\$ 9,247.60

Check Items (Estimated) :S\$ 3,250.70

Total :S\$ 12,498.30

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$

COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.