



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22009095/Kny3m4 Date: 17/10/2022 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGJ 152J	Veh. Inspected	SLZ 202E	
Policy No.	D22MTPV01008601	Coverage (\$)	0.00	
Claim No.	CMTD2203234/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	15/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	BMW 520I (A)	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WBA5A320X0D335127	Colour	METALLIC PEARL WHITE	
Odometer	134607 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R19	GOODYEAR	8 mm	
L/H Front Tyre	245/40 R19	GOODYEAR	8 mm	
R/H Rear Tyre	275/35 R19	GOODYEAR	5 mm	
L/H Rear Tyre	275/35 R19	GOODYEAR	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION & UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/09/2022	Inspection Date	28/09/2022	
Survey held at	60 JALAN LAM HUAT, #04-53 CARROS CENTRE (S) 737869			
Repairer	WIN AUTOMOTIVE SERVICES			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	