

ASS. REC. BY:

REF:

Smo / 22009095/ken

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

Res.: Yes or No

Lum Sum:

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Wilson

Veh No:

Yr Regn:

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / SY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

F - RS

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Not Authorised
 11/12/08
 Repairing After Paint
 4-5 days

WIN AUTOMOTIVE SERVICES
 ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS FOR VEHICLE NO:
 SLZ 202E BMW 520I

Adjustment of Spare Parts Costs for Repairs			Estimate by workshop	
Item	Qty	Vehicle parts description		
1set		front bumper clips	40	✓
	1	front bumper reinforcement	750	X
	1	front bumper sponge	95	✓
	1	front bumper headlamp washer cover	110	✓
	1	front lh fender inner sheild	295	✓
1 set		front lh fender inner sheild fasteners	30	✓
	1	front lh wheel bearing	290	✓
	1	front lh absorber	600	✓
	1	front left lower arm	580	✓
	1	front left wheel hub	750	✓
	1	front grille	290	X
	1	front headlamp lh	4500	✓
	1	front headlamp lower bracket lh	300	✓
	1	front headlamp rh	4500	X
	1	front headlamp lower bracket rh	300	X
	1	front bumper fog lamp lh	380	X
	1	front bumper fog lamp cover lh	190	✓
	1	front bumper	1398	✓
	1	front bumper side retainer	200	✓
	1	front lh fender	980	✓
	1	front lh side mirror assy	2110	X
	1	front windscreen moulding	188	X

Less 5%

Special nett item

front lh rim
 front lh tyre

total parts

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

18876

775.6

14736.4

Red 350 ✓
 300 X

650

Adjustment of Labour Costs for Repairs

Supply paint material to the rear and expandable items:

600 4801

Carry out body cavity preservation

80 X

To remove and replaced damaged parts including straightening and repositioning replacement parts & panel beat	800	480
Check wiring	80	20
to realign headlamp focus	40	20
to programming headlamp function resetting	300	120
remove & reinstall front lh undercarriage components	200	7
to perform 4 wheel alignment	100	60
remove and reinstall front windscreen and conduct water leak test	na	120 X
Total labour	2320	