



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133
T 65 6758 2222 F 65 6257 6931
E sales@scauto.com.sg
scauto.com.sg

Co. Reg. No. 199800107D

M/S TONG TAR TRANSPORT SVC PTE LTD
No 8 Soon Lee Road
SINGAPORE 628072
Insured TONG TAR TRANSPORT SVC PTE LTD
Policy 5128761629-000042

Final Bill

GST Reg. No: 19-9800107D
Date: 29/11/2022
Our Case Ref. SC22/09/122/4TT-TP
Accident Date 12/9/2022

Damaged Vehicle No: PC4513E

S/no	Description	QTY	Price	Disc	Amount
<u>Replaced Parts</u>					
1	REAR BUMPER	1 PC	\$1,980.50	-	\$1,980.50
2	REAR NUMBER PLATE	1 PC	\$80.00	-	\$80.00
3	REAR NUMBER PLATE LIGHT	1 SET	\$855.00	-	\$855.00
4	BODY STICKER	1 PC	\$1,700.00	-	\$1,700.00
5	SUNDRIES	1 PC	\$150.00	-	\$150.00
<u>Labour Charges</u>					
1	LABOUR TO REMOVE AND REINSTALL BODY STICKER	1	\$200.00	-	\$200.00
2	LABOUR TO REMOVE, REINSTALL AND REPAIR REAR BUMPER, REAR PANEL INNER.	1	\$640.00	-	\$640.00
3	LABOUR TO RESPRAY REAR BUMPER	1	\$640.00	-	\$640.00
Sub Total					\$ 6,245.50
Lump Sum					\$ 5,039.40
GST (7%)					\$ 352.76
Total Amount					\$ 5,392.16

Authorised Signature