



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133
 T 65 6758 2222 F 65 6257 6931
 E sales@scauto.com.sg
 scauto.com.sg

Co. Reg. No. 199800107D

ESTIMATE BILL

GST Reg. No: 199800107D
 Date: 16/9/2022
 Our Case Ref: SC22/09/122/4TT-TP
 Accident Date: 12/9/2022

M/S CHINA TAIPING INSURANCE (S)
 PTE LTD
 3 ANSON RD, #16-00 SPRINGLEAF
 TOWER, SINGAPORE 079909
 Insured TONG TAR TRANSPORT SVC PTE LTD
 Policy 5128761629

Damaged Vehicle No: PC4513E

S/no	Description	QTY	Price	Amount	Remark
Replaced Parts					
1	REAR BUMPER <i>Re</i>	1 PC	\$1,980.50	\$ 1,980.50	
2	REAR NUMBER PLATE <i>BT</i>	1 PC	\$ 80.00	\$ 80.00	
3	TAILGATE <i>X Repair</i>	1 PC	\$2,660.50	\$ 2,660.50	
4	REAR NUMBER PLATE LIGHT <i>2's</i>	2 PC	\$ 855.00	\$ 855.00	
5	BODY STICKER <i>1 set</i>	1 SET	\$1,700.00	\$ 1,700.00	
6	SUNDRIES		\$ 200.00	\$ 200.00	
LABOUR CHARGES					
1	LABOUR TO REMOVE AND REINSTALL REAR WIRE HARNESS AND CHECK INTERIOR WIRING ACCORDING TO DAMAGE		\$ 500.00	\$ 500.00	<i>X an</i>
2	LABOUR TO REMOVE AND REINSTALL BODY STICKER		\$ 800.00	\$ 800.00	<i>640?</i>
3	LABOUR TO REMOVE, REINSTALL AND REPAIR REAR BUMPER AND REAR PANEL INNER, REAR LID		\$ 3,200.00	\$ 3,200.00	<i>640</i>
4	LABOUR TO RESPRAY REAR BUMPER, REAR PANEL INNER AND REAR LID.		\$ 2,800.00	\$ 2,800.00	<i>?</i>
5	LABOUR TO CARRY OUT DIAGNOSTIC CHECK		\$ 350.00	\$ 350.00	<i>X an</i>
<i>En. Rial</i> <i>16/9/2022</i> <i>Lump sum repair</i> <i>After repair photos.</i> 3 DAYS					
TOTAL				\$ 15,126.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: