

AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: STRIDES TAXI LTD

DATE: 14/9/2022
VEHICLE NO: SGZ6505B
MODEL: SUZUKI SWIFT
YEAR: 2007-2022
ACCIDENT DATE: 14/9/2022
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: loulisongautowheels@yahoo.com

ESTIMATE

DESCRIPTION	QTY	LIST PRICE
PARTS		
RH FRONT DOOR / 00	1	\$ 1,055.60 ✓
RH REAR DOOR / 00	1	\$ 1,011.50 ✓
<i>Plot</i> RH REAR DOOR INNER TRIM BOARD <i>1</i> X	1 NN	\$ 478.60
RH REAR DOOR INNER TRIM BOARD <i>1</i> SET X	NN	\$ 30.00
CLIPS		
RH REAR DOOR BLACK TAPE / <i>MC</i> SET		\$ 199.50 ✓
RH REAR GLASS REGULATOR <i>1</i> X NN	1	\$ 343.20
RH REAR DOOR REGULATOR MOTOR <i>1</i> X NN	1	\$ 355.30
RH REAR DOOR ACTUATOR X NN	1	\$ 387.50
RH REAR DOOR OUTER MOULDING X NN	1	\$ 199.90
RH REAR DOOR W/STRIP <i>1</i> X NN	1	\$ 198.50
RH REAR FENDER X NN	1	REPAIR
RH ROCKER PANEL X R	1	REPAIR
REAR BUMPER X NN	1	\$ 789.60
RH REAR BUMPER RETAINER X NN	1	\$ 88.50
REAR BUMPER CLIPS X NN SET		\$ 30.00
RH REAR MUDFLAP X NN	1	\$ 166.50
RH TAIL LAMP X NN	1	\$ 798.60
TOTAL:		\$ 6,132.80
DISCOUNT 15%:		\$ 919.92
		\$ 5,212.88

2266.60
-15%
1926.61

S/NET	PRICE
RH REAR RIM X NN	\$ 550.00

LABOUR	PRICE
LABOUR FOR FACILITATE REPAIR	\$ 1,000.00 <i>400</i>
TO RESPRAY RH REAR FENDER	\$ 300.00 X
TO RESRAY REAR BUMPER	\$ 300.00 X
TO RESPRAY RH ROCKER PANEL	\$ 300.00 <i>200</i>
TO RESPRAY RH FRONT DOOR	\$ 300.00 <i>200</i>
TO RESPRAY RH REAR DOOR	\$ 300.00 <i>200</i>

AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: STRIDES TAXI LTD

DATE: 14/9/2022
VEHICLE NO: SGZ6505B
MODEL: SUZUKI SWIFT
YEAR: 2007-2022
ACCIDENT DATE: 14/9/2022
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATE

TO CHECK AND RECONNECT ALL NECESSARY WIRING
TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR
TO REMOVE AND REFIT BOTH DOOR COMPONENT
WHEEL ALIGNMENT
TO ROTATE AND BALANCE RH REAR RIM
SUNDARIES
RUST PROOFING

\$ 30	50.00
\$ 50	150.00
\$ 100	300.00
\$ 80	100.00 X
\$	80.00 X
\$ 30	80.00
\$ 30	100.00
TOTAL: \$	3,360.00

1240

TOTAL: \$	9,122.88
7% GST: \$	638.60
\$	9,761.48

3166.61

L/S - 2533.28
= 2550

repair limit \$2000

Steve (LKK) 8322 8813
19/9/22, 10.30~

m L
L/S
h AL y
S d/s

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: