

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKG 1013P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET (NPA)	NOT NECESSARY	-	-
1	FRONT BUMPER	BROKEN	1,850.00	1,789.00
1	FRONT BUMPER RETAINER RH	NOT NECESSARY	280.00	-
1	FRONT BUMPER SPONGE	CRACKED	398.50	155.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	680.00	-
2	FRONT BUMPER SENSOR RH	CUT	560.00	305.00
1	FOG LAMP GARNISH RH	NOT NECESSARY	339.00	-
1	FRONT FENDER RH (ALLOY)	BUCKLED	685.00	685.00
1	FRONT FENDER UNDERSHIELD RH	NOT NECESSARY	383.45	-
1	FRONT SUPPORT PANEL (NPA)	NOT NECESSARY	-	-
1	HEADLAMP RH	CUT	3,985.60	3,617.00
1	HEADLAMP LOWER BRACKET RH	BROKEN	220.00	120.00
	LESS 10% DISCOUNT		-938.16	-667.10
			8,443.39	6,003.90
	SPECIAL NETT ITEMS			
10	FRONT BUMPER CLIPS (SN)	NECESSARY	55.00	55.00
15	FRONT BUMPER RIVETS (SN)	NOT NECESSARY	225.00	-
			280.00	55.00
	<u>LABOUR</u>			
	LABOUR CHARGES REPAIR, REPLACE, ALIGN ADJUST ETC.		800.00	400.00
	TO DO ANTI RUST.		90.00	60.00
	TO CHECK LAMP WIRING SYSTEM, FOCUS HEADLAMP ETC.		120.00	30.00
	TO DO COMPUTER SETTLING AFTER REPAIR.	NOT NECESSARY	280.00	-
	TO DO SPRAY PAINTING ON AFFECTED AREA INNER OUTER.		1,000.00	400.00
			2,290.00	890.00
	GRAND TOTAL		11,013.39	6,948.90

Report Ref No. CS/GAI22009101/Gwy3m4



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		5,550.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/GAI22009101/Gwy3m4

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

X.S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.