



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile		CS3/SMO22005349/Kny3-1	
SOMPO INSURANCE SINGAPORE PL		Ref: CS/SMO22005349/3	
50 RAFFLES PLACE #03-03		Date: 00/00/2022 16/09/2022	
SINGAPORE LAND TOWERS SINGAPORE 048623		Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMU 1458S	Veh. Inspected	SLM 33U
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2201933/MYE	Excess (\$)	0.00
Assign From	GRACE TEO MELVIN YE	Assign Date	00/00/2022 16/09/2022
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	01/06/2022	Inspection Date	
Survey held at	LIM MOTOR PTE LTD 160 SIN MING DRIVE #05-20 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

ASS. REC. BY:

REF:

SMO/ 22005349/Kny3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

2:30pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP 24 HRS

01/31

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SUM 334

Yr Regn:

01, 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Ferrari 458

C.C

4497

Colour

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

56013

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

EIF87NHC 000178228

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

265/30 ER21

R:

325/25 ER21

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

1/6/22

D.O.I.

13/6/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

PRS

13/7/22 3pm

En repair 8/8-25/c

Spoken to Peter Lim, only conduct PRS and no estimate given. He said parts need 1-2 months to arrive so he will let us resurvey dismantle when the parts arrived.

13/7/22 Submit PRS

Repair range \$18K - 25K

3/10

Lump Sum \$21,350 and 2 days (Red, 4800, 18%)

Date/Time, File Pass to?



: Prell. Report

1) 13/7/22



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS - SI

Fees

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format:

PRS

Lump Sum / I.B.I. (\$



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0413 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle Inspection Report

To: Chua Yi Sheng
C/o: 160 Sin Ming Drive #05-20
Sin Ming AutoCity (S) 575722

Date of report: 25.08.2022
Date of request: 13.06.2022
Date of inspection: 13.06.2022
Date of accident: 01.06.2022
Claim type: Third Party Claim

Report No: AAS/2022/108

Particulars of affected vehicle:

Registration no: SLM33U
Make/Model: Ferrari 458 Italia 4.5 (A)
Year of registration: 2010/11
Colour: Metallic Red

Odometer: 56013 km
Engine Capacity: 4497 cc
Engine no: 168309
Chassis no: ZFF67NHC000178228

Condition of tires:

Front Left: 6mm
Make: Pirelli
Rear Left: 6mm
Make: Pirelli

Front Right: 6mm
Make: Pirelli
Rear Right: 6mm
Make: Pirelli

Type of road wheel: Alloy (The above represent the remaining life of the tire thread)

Pre-accident condition (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : In order
Footbrake : In order
Steering : In order
Apparent engine modification : Nil

The Assignment

The inspection was conducted at M/s. Lim Motor Pte Ltd
160 Sin Ming Drive #05-20
Sin Ming AutoCity (S) 575722

(Subsequent inspection was conducted)

Assessment

Repairer's estimate: \$ 42,032.65
Revised estimate: \$ 32,712.65
Recommended reserve: \$ 26,150.00 (Lump sum)

Estimated normal duration of repairs : 2 Working days



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0418 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle No: SLM33U

Report No: AAS/2022/108

W/O PREJUDICE

Point of impact

At the rear portion.

General description of damages

The rear bumper diffuser, etc.

Other parts were also found damaged. (See schedule for details)

Recommendation

The estimate cost of repair submitted by M/s Lim Motor Pte Ltd as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$32,712.65

Conclusion

The repairer has agreed to undertake the repair at a lumpsum of SGD \$26,150.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of 2 working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a '**Without Prejudice**' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 58 photographs.

Your Faithfully
Absolute Appraisal Services Pte Ltd



Nicky Seah
Automobile Appraiser
MSAAA / MSMCTA



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0413 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle No: SLM33U

Report No: AAS/2022/108

Appraisement Schedule

S/N	Parts Description	Qty	Condition	Repairer's Est	Revised Est
1	Centre rear trellis	1	Dented	\$ 502.65	\$ 502.65
2	Rear bumper crossmember	1	Refit	\$ 8,900.00	-

List total: \$ 9,402.65 \$ 502.65

1	Rear bumper diffuser (Misha)	1	Cracked	\$ 31,400.00	\$ 31,400.00
2	Rear number plate	1	Cracked	\$ 180.00	\$ 180.00

Special nett total: \$ 31,580.00 \$ 31,580.00

Parts Total: \$ 40,982.65 \$ 32,082.65

S/N Labour Description

1	Renew damaged parts, re-align affected area.	Repairer's Est	Revised Est
		\$ 1,000.00	\$ 600.00
2	Check lightings & wirings.	\$ 50.00	\$ 30.00

Labour Total: \$ 1,050.00 \$ 630.00

Grand Total: \$ 42,032.65 \$ 32,712.65

The final adjusted lump sum amount is \$26,150.00

Under normal circumstances, the repair should be completed within a reasonable period of 2 working days. ✓

58 Photographs were taken at the time of inspection.

821,350

Disclaimer: This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by Absolute Appraisal Service Pte Ltd for any reliance on this report by any third party.