



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22009134/Evy3m4 Date: 18/10/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMB 5017E	Veh. Inspected	SFY 5758L
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/09/22/5015	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	16/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	KIA STINGER	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	KNAE351AMK6060505	Colour	WHITE
	Odometer	47640 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/50 R17	DUNLOP	4 mm
	L/H Front Tyre	215/50 R17	DUNLOP	4 mm
	R/H Rear Tyre	215/50 R17	DUNLOP	4 mm
	L/H Rear Tyre	215/50 R17	DUNLOP	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/09/2022	Inspection Date	16/09/2022
	Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	