



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
SOH SENG KEE	Cust No/Name /SOH SENG KEE
17 GALISTAN AVENUE	Reg No/Reg Date SFY5758L / 28/03/201
SINGAPORE 669691	Date In/Mileage / 0
Contact No Mobile: 98385385	Chassis No KNAE351AMK6060505
	Engine No G4CLKH020371
	Make/Model KIA/STINGER 2.0 A GAA4
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	13/09/2022/ 19:30	TLC	442 / CocoLu	57355

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPAIR REAR BUMPER, RENEW BUMPER LOWER COVER				640.00 ✓
E PNT88000 REMOVE & INSTALL PARKING SENSOR				80 ✓ 100.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER				550.00 ✓
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM				50.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				280.00 ✓
M SUNDRY REDO REAR BUMPER FILM				600.00 ? X
M SUNDRY Sundry				20.00 ✓
M COVER-RR BUMPER LWR	1.00	342.00	00.00	342.00 ✓

**Estimate**

(Invoice &amp; Certificate)

TBA

cut

Steve (LKK)  
16/9/22, 1.00pm

WLR  
P/P  
by Bly  
3 Lys

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Confirm & accepted by

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Authorized signatory and company stamp

	Nett	2,582.00
7% GST on	2582.00	180.74
<b>Total Payable</b>		<b>2,762.74</b>

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.