



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
EHSAN AHMED SAYEEM CHOWDHURY	Cust No/Name LCV18546/Mr Ehsan Ahmed Sayeem Chowdhury
264 TOA PAYOH EAST	Reg No/Reg Date SNH744D / 28/07/202
#08-32	Date In/Mileage / 0
SINGAPORE 310264	Chassis No KNARH81GMN5119757
Contact No	Engine No G4FTNH330596
	Make/Model KIA/SORENTO 1.6 A SR G583
	Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LCV18546	CRDVCH	15/09/2022/ 14:38		442 / CocoLu	57431		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							520.00
RENEW REAR BUMPER LOWER COVER, REPAIR REAR BUMPER							
E PNT98000							450.00
SPRAY PAINT FOR REAR BUMPER							
E PNT88000							80.00
REMOVE & INSTALL PARKING SENSOR							
A 90000001							50.00
CHECK WIRING & ELECTRICAL SYSTEM							
A 10028901							160.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
M SUNDRY							20.00
Sundry							
M COVER-RR BUMPER LWR				1.00	565.00	00.00	565.00
M SKID PLATE-RR BUMPER				1.00	120.00	00.00	120.00
M PIECE-SKID PLATE NO.1				1.00	10.00	00.00	10.00
M MOULDING ASSY-RR BUMPER,CTR				1.00	66.00	00.00	66.00
M LAMP ASSY-REAR FOG				1.00	127.00	00.00	127.00
M ULTRASONIC SENSOR ASSY-P.A.S				1.00	171.00	00.00	171.00

Confirm &amp; accepted by

	<b>Nett</b>	<b>2,339.00</b>
7% GST on	<b>2339.00</b>	<b>163.73</b>
<b>Total Payable</b>		<b>2,502.73</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.