



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref: <del>CS3/ASM22001751/Tqy3</del>		
8 SHENTON WAY #24-01		Date: <del>20/02/2022</del> 16/09/2022		
AXA TOWERSINGAPORE 068811		Code: ASM		
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	SHA 1736D	Veh. Inspected	SNB 6476U	
Policy No.		Coverage (\$)	0.00	
Claim No.	S2M03TWZ	Excess (\$)	0.00	
Assign From	<del>ONG KIAN THIENG DERICK</del> OH VALE	Assign Date	<del>22/02/2022</del> 16/09/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	21/02/2022	Inspection Date	24/02/2022	
Survey held at	MOTOREN AUTOMOTIVE SOLUTIONS LLP 68 KAKI BUKIT AVENUE 6, #01-20, ARK@KB, SINGAPORE 417896			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				