

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0799/2022/EQ
DATE : 15-Sep-22
WIP : 41995

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/09/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

6 days exclude 1 Sunday

2 Dec 22 - Johnny Boo

OWNER'S NAME : MS CHAN CHUI FUNN
ADDRESS : 87 PASIR PANJANG HILL
#02-12, KENTVIEW PARK
SINGAPORE 118892
TELEPHONE : HP +65 96796038
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800031230-04
VEHICLE NO : **SLX 4854 H**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 28/3/2018
ENGINE NO : CVK 056464
CHASSIS NO : WAUZZZF43JA124722
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 14-Sep-22
PLACE OF ACCIDENT : CROSS ST & CECIL ST

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLX 4854 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	\$ 480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	\$ 250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	
4	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$ 280.00	\$ 280.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,200.00	\$ 1,200.00
TOTAL LABOUR CHARGES		\$ 6,710.00	\$ 2,210.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLX 4854 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>	\$ 2,210.00
6	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS FRONT DOOR.	\$ 3,500.00	\$ 1,650.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 10,402.00	\$ 4,052.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 4854 H

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,377.00	\$	1,901.60
2	FRONT BUMPER FIXING PARTS	1	\$ 612.00		
3	FRONT BUMPER SECURING STRIP	2	\$ 79.00		
4	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00		
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 254.00	\$	203.20
6	RADIATOR AIR GUIDE - LH	1	\$ 72.00		
7	RADIATOR GRILLE	1	\$ 1,478.00		
8	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 151.00		
9	FRONT BUMPER FOAM FILLER PIECE	1	\$ 139.00		
10	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00		
11	FRONT BUMPER GUIDE SECTION - LH	1	\$ 41.00	\$	32.24
12	FRONT BUMPER TOP COVER	1	\$ 143.00		
13	CAUTION SIGN STICKER	1	\$ 16.00		
14	AIR CONDITIONER STICKER	1	\$ 9.00		
15	FRONT BUMPER BRACKET	1	\$ 154.00	\$	122.80
16	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00		
17	HORN HIGH TONE - LH	1	\$ 134.00		
18	HORN BRACKET - LH	1	\$ 33.00		
19	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$ 531.00		
20	FRONT PARKING AID SEAL RING	4	\$ 10.00		
SUB TOTAL SPARE PARTS		:	\$ 7,415.00	\$	2,259.84

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 4854 H

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	<i>2,259.84</i>
21	FRONT BUMPER WIRING SET	1	\$ 567.00		
22	FRONT FENDER - LH	1	\$ 861.00	\$	<i>688.80</i>
23	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 32.72	\$	<i>64.24</i>
24	FRONT FENDER BRACKET - LH	1	\$ 41.00	\$	<i>32.72</i>
25	FRONT FENDER RIVET	7	\$ 27.00	\$	<i>21.28</i>
26	FRONT FENDER BRACE - LH	1	\$ 132.00	\$	<i>105.20</i>
27	FRONT DEFORMATION ELEMENT BRACKET - LH	1	\$ 55.00		
28	FRONT WHEEL HOUSING LINER - LH	1	\$ 260.00	\$	<i>208.00</i>
29	FRONT WHEEL SPOILER	1	\$ 82.00	\$	<i>65.12</i>
30	FRONT SPOILER END PLATE - LH	1	\$ 39.00		
31	FRONT FENDER OUTER LEDGE COVER - LH	1	\$ 35.00	\$	<i>27.52</i>
32	FRONT FENDER LEDGE COVER - LH	1	\$ 26.00	\$	<i>20.16</i>
33	HEADLIGHT - LH	1	\$ 8,294.00	\$	<i>6,635.20</i>
34	HEADLIGHT POWER MODULE	1	\$ 842.00		
35	HEADLIGHT CONTROL UNIT	1	\$ 840.00		
36	COMPENSATING PIECE	3	\$ 137.00		
37	HEADLIGHT HOSE - LH	1	\$ 42.00		
38	LIFT CYLINDER - LH	1	\$ 231.00		
39	LIFT CYLINDER BRACKET	1	\$ 7.00		
40	LIFT CYLINDER CORRUGATED PIPE	1	\$ 107.00		
SUB TOTAL SPARE PARTS		:	\$ 12,657.72	\$	<i>10,128.08</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 4854 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 10,128.08
41	LOCK CARRIER	1	\$ 1,478.00	
42	LOCK CARRIER SUPPORT - LH	1	\$ 43.00	
43	RADIATOR AIR GUIDE - LH	1	\$ 32.00	
44	RADIATOR AIR GUIDE - LH	1	\$ 14.00	\$ 10.88
45	RADIATOR AIR DUCT - UPPER	1	\$ 19.00	
46	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00	
47	READY-MIX COOLANT	6	\$ 297.00	
48	FRONT NO PLATE	S/N	\$ 60.00	
49	SUPPLEMENTARY		\$ 14.00	\$ 10.88
5-	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS			: \$ 22,450.72	\$ 10,149.84
TOTAL LABOUR CHARGES			: \$ 10,402.00	\$ 4,052.00
GRAND TOTAL			: \$ 32,852.72	\$ 14,201.84

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

BL-31/10/22



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0799/2022/EQ 26-Sep-22 CHANG 1 of 1 SLX 4854 H AUDI A4 SEDAN 2.0 TFSI
Quantity	Description	Unit Price	Amount
Parts			
1	RADIATOR AIR GUIDE - RH	\$ 14.00	\$ 10.89
	GRAND TOTAL	\$ 14.00	\$ 10.88

For Premium Automobiles Pte Ltd

Authorised Signature