

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

ATA 413034?

Date / Time

Action / Instruction

28/9/22 2/5 43300 in hand Susan.

Veh No:

GBJ2663Y

Yr Regn:

04/03/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CM /

Make:

Mit Canter FEA01 c.c 2998

Colour

brnze

A/C: Insured / Std / NI / NA

Sp. Reading

100014

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

FEA01BA 30065

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Austone

Front

Rear

R/Bal.

6

mm

R/Bal.

6/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

27/08/22

D.O.I.

16/09/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S dit

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) ___ S + RS, ___ SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$



Liu's Brother Auto Engineering Workshop

No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

UEN No: 53291793J

liusbro@gmail.com

Tel: 67411730

ESTIMATE

Name: Allianz Insurance Company of Singapore Pte Ltd
Address: Motor Claims Department
12 Marina View #14-01
Asia Square Tower 2 Singapore 018961

Ref Date: 15-09-2022
Ref No: GBJ2663Y220827
Vehicle No: GBJ2663Y
Model / Make: Mitsubishi Canter
Capacity: FEA01BR2SDEK (CBU)

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Front Lh	Door / 665- body	\$ 1,995.00	1	\$ 1,995.00		✓
2		Door Outer Garnish 182-40 merged 102	\$ 315.00	1	\$ 315.00		✓
3		Door "ROC" Sticker	\$ 48.00	1	\$ 48.00	SN	30 s/n
4		Corner Panel 408-15 C12	\$ 486.90	1	\$ 486.90		✓
5		Corner Panel Clips 1 set 11	\$ 28.00	1	\$ 28.00	SN	X
6		Signal Lamp 208-21 320	\$ 324.30	1	\$ 324.30		✓
7		Head Lamp 566-01 C12	\$ 856.40	1	\$ 856.40		✓
8		Head Lamp Side Garnish 412 side lamp 3/20	\$ 976.00	1	\$ 976.00		180.
9		Bumper	\$ 1,127.60	1	\$ 1,127.60		X
10		Bumper Side 319-82 green	\$ 441.70	1	\$ 441.70		✓
11		Bumper Side Clips 01 set 11	\$ 65.00	1	\$ 65.00	SN	X
12		Step Panel Outer Lower 115 311-20 31021	\$ 623.00	1	\$ 623.00		✓
13		"Corporate" Advertisement & Artwork	111		\$ 300.00	SN	150 s/n
14		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc			\$ 700.00	-	550
15		To putty & spray painting & including touch up paint on accident affected areas			\$ 600.00		500
		To apply Rust Proofing, reseal tuff-coating treatment on accident area			\$ 40.00		30

Total Parts & Labour of estimate for damaged vehicle

\$ 8,926.90

Total amount in Lumpsum Basis for repaired vehicle

\$ -

SDL

not Authorized
16/09/22
2/s # 3300
Emphe. Hw ngn
4 days

Liu's Bro Auto Engrg Wks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-3840.89
252
2880.66
180
1080
4140.66
292
3312