

Main Office:

 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel : (65) 6476 3333
 Fax : (65) 6271 5891
 www.mova.com.sg

Workshop Dept:

 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722
 Tel : (65) 6272 3892
 Fax : (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Estimate

16/09/2022

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Page # :- 1

Veh # :- SNC1212S

Veh Model :- VOLVO XC40 T5

Estimate# :- CK423985

Claim # :-

ACC. Date :- 14/09/22

Terms :- C.O.D Days

Remarks :-

Attention :- XA018

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR TAILGATE	1 PC	3,430.00	3,430.00
2.	REAR TAILGATE "VOLVO" EMBLEM	1 PC	162.00	162.00
3.	REAR TAILGATE "XC40" EMBLEM	1 PC	162.00	162.00
4.	REAR TAILGATE "T5" EMBLEM	1 PC	105.00	105.00
5.	REAR TAILGATE "AWD" EMBLEM	1 PC	125.00	125.00
6.	REAR TAILGATE INNER LOCK	1 PC	476.00	476.00
7.	REAR TAILGATE INNER TRIM COVERING	1 PC	793.00	793.00
8.	REAR TAILGATE INNER TRIM UPPER COVERING LH	1 PC	528.00	528.00
9.	REAR TAILGATE INNER TRIM UPPER COVERING RH	1 PC	528.00	528.00
10.	REAR TAILGATE UPPER HINGE RH	1 PC	108.00	108.00
11.	REAR TAILGATE PULL HANDLE GARNISH	1 PC	235.00	235.00
12.	REAR TAILGATE WIPER MOTOR	1 PC	830.00	830.00
13.	REAR W/SCREEN GLASS	1 PC	1,580.00	1,580.00
14.	REAR W/SCREEN SEAL	1 PC	220.00	220.00
15.	REAR BUMPER	1 PC	2,015.00	2,015.00
16.	REAR TAILLAMP RH	1 PC	1,320.00	1,320.00
17.	REAR SIDE BUMPER RH	1 PC	640.00	640.00
18.	REAR END PANEL (REPAIR)	1 PC		
19.	REAR QUATER PANEL RH (REPAIR)	1 PC		
LIST TOTAL S\$				13,257.00
10% DISCOUNT S\$				-1,325.70
				11,931.30
SPECIAL NET ITEMS :				
1.	REAR TAILGATE INNER TRIM COVERING CLIPS	1 SET	50.00	50.00
2.	REAR W/SCREEN TINTED	1 PC	350.00	350.00
3.	REAR W/SCREEN SEALANT	1 PC	40.00	40.00
4.	REAR VIDEO CAMERA	1 PC	400.00	400.00
5.	REAR BUMPER CLIPS	1 SET	60.00	60.00
SPECIAL NET TOTAL S\$				900.00
LABOUR :				
TO REMOVE, REPLACE REAR W/SCREEN GLASS, REAR W/SCREEN SEAL, REAR W/SCREEN SEALANT & ETC.				120.00
TO REMOVE, REPLACE, REFIT REAR TAILGATE INNER MECHANISM SUCH AS REAR TAILGATE INNER COVERING, REAR TAILGATE INNER LOCK, REAR TAILGATE CENTRAL LOCKING SYSTEM & ETC. TO EFFECT REPLACE OF REAR TAILGATE				130.00
TO REMOVE, REFIT REAR BUMPER REVERSE SENSOR, REAR VIDEO CAMERA & ETC. TO EFFECT REPLACE OF REAR BUMPER, REAR TAILGATE & ETC.				100.00
bizSAFE TO REMOVE, REPLACE, REPAIR, READJUST REAR ACCIDENT AREAS SUCH AS REAR TAILGATE, REAR				

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: **(65) 6476 3333**
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722
 Tel: **(65) 6272 3892**
 Fax: (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Estimate

16/09/2022

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- XA018

Page # :- 1 147034
 Veh # :- SNC1212S
 Veh Model :- VOLVO XC40 T5
 Estimate# :- CK423985
 Claim # :-
 ACC. Date :- 14/09/22
 Terms :- C.O.D Days
 Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	BUMPER, REAR END PANEL, REAR BUMPER LOWER LIP & REAR QUATER PANEL RH BACK TO ORIGINAL CONDITIONS			800.00
	TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR QUATER PANEL RH, REAR END PANEL & ETC.			900.00
	TO CHECK WIRING & ELECTRICAL SYSTEM			80.00
	TO DIAGNOSIS FAULTY CODE & RESET MEMORY			180.00
	LABOUR TOTAL S\$			2,310.00

E. & O.E

NON-TAX AMOUNT S
 AMOUNT S\$ 15,141.30
 GST @ 7 % 1,059.89
 AMOUNT DUE S\$ 16,201.19

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**