

ASS. REC. BY: Steve

CS/CT1 22009151/Eng1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKE2111T Yr Regn: 176/22
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: BMW 1X3 c.c. Electric car
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 10450 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WBY 4904 280547 6535
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brakes: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 275/40R20
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or .

Front Rear
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 15/9/22 Performance D.O.I. 10/11/22
 Survey held at
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MV 280K</u>

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / I.B.H. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

Thurs 10/11 @ 10am
S&R

SKE2111T

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

Stew (CLKK)

10/11/22, 19.00ch

W R, P/P, M BL CESTIMATE
4 djs

GST REG. NO : M2 - 0020081 - X

15/9/22

Estimate No. : b1 63318	Page No. : 1 of 5
Date Estimated : 15/09/2022	
Prepared By : Han Kwan Yong	

- ESTIMATE REPAIR FOR - Tan Kok Soon Benjamin 30 Watten Rise Singapore 287327	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKE2111T	WBY42DU080S426535	17/06/2022	1X3	493

DESCRIPTION	VALUE
To replace rear bumper and to make good boot lid	1775 2,550.00
To respray rear bumper and boot lid	1972 2,076.00
To remove old PDC assembly, re place damaged parts and reconnect to new bumper including re connect to new bumper and conduct check for proper function.	168 177.00
To check electrical wiring system and lighting at the rear section for proper function.	168 177.00
Sundries	80.00
Total Labour 1:	5,060.00

DESCRIPTION	QTY	PRIC	VALUE
EXPANDING RIVET / MC	10	2.55	25.50
# REAR BUMPER PANEL PRIMED (PD / DO	1	1,593.30	1,593.30
# REAR BUMPER BOTTOM TRIM PANE / CMT	1	297.75	297.75
REAR RH COVERING X	1	80.85	80.85
REAR BUMPER CARRIER (BEV) ?	1	776.85	776.85
REAR RH BUMPER MOUNT ?	1	118.75	118.75
# REAR BUMPER COVER PAINTED (F / CMT (silver)	1	274.35	274.35
REAR BUMPER TOWING EYE COVER ?	1	48.80	48.80
# ADAPTER FOR SUPPORT REAR	1	166.90	166.90
# RH BOTTOM COVER (BLUE) / CMT (Blue)	1	109.25	109.25
REAR RH BUMPER MOUNT ?	1	209.70	209.70
EMBLEM GROMMET - MC	2	0.95	1.90
# PLAQUE ? / MC	1	72.85	72.85
# Underbody sh ?	1	79.50	79.50
# UNDERBODY PANELLING REAR END ?	1	102.20	102.20
RH REFLECTOR (M) / BR	1	39.80	39.80
DECOUPLING RING / MC	1	5.30	5.30
ULTRASONIC SENSOR BLACK ?	1	254.05	254.05
Total Parts :			4,257.60

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 63318
Date Estimated : 15/09/2022
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKE2111T	WBY42DU080S426535	17/06/2022	ix3	493

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	5,060.00
Parts	:	4,257.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	652.23
Grand Total	:	<u>9,969.83</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **