



## Final Report

Estimate No. : **b1 63318**  
Date Estimated : **15/09/2022**  
Prepared By : **Han Kwan Yong**

Page No. :

**- ESTIMATE REPAIR FOR -**

**Tan Kok Soon Benjamin**  
**30 Watten Rise**

**Singapore 287327**

**- ACCOUNT - 135**

**China Taiping Insurance (S) Pte Ltd**  
**3 Anson Road**  
**#16-00 Springleaf Tower**  
**Singapore 079909**

|                 |                          |                   |            |            |
|-----------------|--------------------------|-------------------|------------|------------|
| REGN. NO.       | CHASSIS NO.              | REGN. DATE        | MODEL      | M LEAGE    |
| <b>SKE2111T</b> | <b>WBY42DU080S426535</b> | <b>17/06/2022</b> | <b>iX3</b> | <b>493</b> |

| DESCRIPTION                                                                                                                            | ORIGINAL PRICE | DISC. % | NETT     |
|----------------------------------------------------------------------------------------------------------------------------------------|----------------|---------|----------|
| To replace rear bumper and attachments, RH bottom cover include making good the boot lid and knocking out dents caused by the accident | 1,275.00       | 0.00    | 1,275.00 |

|                                         |          |      |          |
|-----------------------------------------|----------|------|----------|
| To spray paint rear bumper and boot lid | 1,972.00 | 0.00 | 1,972.00 |
|-----------------------------------------|----------|------|----------|

|                                                                                                                                                       |        |      |        |
|-------------------------------------------------------------------------------------------------------------------------------------------------------|--------|------|--------|
| To remove old PDC assembly, replace damaged parts and reconnect to new bumper including reconnect to new bumper and conduct check for proper function | 168.00 | 0.00 | 168.00 |
|-------------------------------------------------------------------------------------------------------------------------------------------------------|--------|------|--------|

|                                                                                        |        |      |        |
|----------------------------------------------------------------------------------------|--------|------|--------|
| To check electrical wiring system and lighting at the rear section for proper function | 168.00 | 0.00 | 168.00 |
|----------------------------------------------------------------------------------------|--------|------|--------|

|          |       |      |       |
|----------|-------|------|-------|
| Sundries | 80.00 | 0.00 | 80.00 |
|----------|-------|------|-------|

| DESCRIPTION                          | UNIT PRICE | QTY   | DISC. % | NETT     |
|--------------------------------------|------------|-------|---------|----------|
| REAR BUMPER PANEL PRIMED (PDC+PMA)   | 1,593.30   | 1.00  | 0.00    | 1,593.30 |
| REAR BUMPER BOTTOM TRIM PANEL (GLOS) | 297.75     | 1.00  | 0.00    | 297.75   |
| REAR BUMPER COVER PAINTED (FROZEN G) | 274.35     | 1.00  | 0.00    | 274.35   |
| RH BOTTOM COVER (i BLUE)             | 109.25     | 1.00  | 0.00    | 109.25   |
| EMBLEM GROMMET                       | 0.95       | 2.00  | 0.00    | 1.90     |
| PLAQUE 82MM                          | 72.85      | 1.00  | 0.00    | 72.85    |
| # LETTERING (i X3)                   | 98.35      | 1.00  | 0.00    | 98.35    |
| EXPANDING RIVET BLACK                | 1.40       | 15.00 | 0.00    | 21.00    |
| RH REFLECTOR (M)                     | 39.80      | 1.00  | 0.00    | 39.80    |

**Performance Motors Limited.**

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269  
Co Reg No. 197401559W





## Final Report

### # SUPPLEMENTARY ITEMS

|                                 |          |
|---------------------------------|----------|
| Total Labour :                  | 3,663.00 |
| Total Parts :                   | 2,508.55 |
| Total Labour & Parts :          | 6,171.55 |
| Deduction for Excess :          |          |
| Total Repair Costs less Excess: | 6,171.55 |
| GST @7%:                        | 432.01   |
| Grand Total :                   | 6,603.56 |