



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22009152/Uny3q2 Date: 06/10/2022	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLH 3379D	Veh. Inspected	GBJ 3545Z	
Policy No.	P10255300R02	Coverage (\$)	0.00	
Claim No.	C10017406/CD	Excess (\$)	0.00	
Assign From	SALIZAWATI HAIZAR	Assign Date	16/09/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA HIACE (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTFHT02P000248633	Colour	WHITE	
Odometer	63806 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195 R15	AUSTONE	6 mm	
L/H Front Tyre	195 R15	AUSTONE	6 mm	
R/H Rear Tyre	195 R15	AUSTONE	6 mm	
L/H Rear Tyre	195 R15	AUSTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	07/09/2022	Inspection Date	16/09/2022	
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	