

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988

Our File No: CS/EGI22009155/EVY3Q2**Date:** 25/10/2022REFERENCE

Insured/Claimant: - Policy No: -
Date of Loss: 10/09/2022 Nature of Claim: OD Claim No: CDMPG22001886

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMT6430T**
Make & Model: BMW 520I, 2.0 (A) Engine No: 24715978B48B20A
Reg. Date: 09/07/2020 (Man. Year: 2020) Chassis No: WBAJR12030CE36479
Colour: Silver Odometer: 36800 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$200,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18 Rear Tyre Size: 245/45 R18
Front Left Side: Hankook 4 mm Rear Left Side: Hankook 4 mm
Front Right Side: Hankook 4 mm Rear Right Side: Hankook 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,771.75	6,495.05	276.70	4.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,549.00	2,629.00	920.00	25.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,320.75	9,124.05	1,196.70	11.60
- Excess (S\$)	700.00	700.00	0.00	0.00
(S\$)	9,620.75	8,424.05	1,196.70	12.44
+ GST 7.00/7.00% (S\$)	673.45	589.68	83.77	12.44
Nett Amount (S\$)	10,294.20	9,013.73	1,280.47	12.44

INSPECTION

Date of Assignment: 16/09/2022
Date Inspected: 26/09/2022 Inspected At: Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby Performance Centre
Singapore 159941
Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Oct 2022)
Parts:	143	BMW 520I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMT6430T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*LH FOG LAMP SUPPORT	Not Necessary	67.15 FS	*- FS
3	1		*RH FOG LAMP SUPPORT	Not Necessary	67.15 FS	*- FS
4	1		*LH GUIDE TOP	Not Necessary	36.20 FS	*- FS
5	1		*RH GUIDE TOP	Not Necessary	36.20 FS	*- FS
6	1		*FRT BUMPER PANEL PRIMED (PMA/PDC)	Crushed	1,454.15 FS	*1,454.15 FS
7	1		*LH HEADLIGHT LED AHL HIGH (ICON LIG)	Broken	4,960.90 FS	*4,960.90 FS
					Total Parts (\$\$)	6,771.75
						6,495.05

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER	New	1,700.00	850.00
2	TO RESPRAY FRONT BUMPER	New	1,038.00	986.00
3	TO CHECK ELECTRICAL WIRING	New	177.00	168.00
4	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
5	TO REPLACE LH HIGH INTENSITY HEADLIGHT INCLUDE FUNCTIONALITY PROGRAMMING AND CONDUCTING CHECKS FOR PROPER FUNCTION	New	457.00	457.00
Gross Labour Cost (\$\$)			3,549.00	2,629.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >