LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

From:

LKK Auto Consultants Pte Ltd

To: ERGO Insurance Pte. Ltd. 8 Temasek Boulevard #04-01 Suntec Tower Three

8 Temasek Boulevard 51 Ubi Ave 1 #01-25 #04-01 Suntec Tower Three Paya Ubi Industrial Park Singapore 038988 Singapore 408933

Attn: Date: 27 Sep 2022

Preliminary Advice

Vehicle No : SMT6430T Accident Date : 10/09/2022

Make : BMW 520I Policy No. : -

Assignment Date : 16/09/2022 Excess : \$\\$0.00 Date of Inspection : 26/9/2022 Est. Duration of Repair : 3

Inspection At : PERFORMANCE MOTORS LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,863.75
Revised Amount	:S\$	8,773.25
Check Items (Estimated)	:S\$	67.15
Total	:S\$	8,840.40

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
1 tow for Old Value	.Οψ

 Pre-Accident Value
 :S\$ 200,000.00

 COE / PARF Rebate
 :S\$ 77,614.00

Salvage Value :S\$

Margin for Repair :S\$ 122,386.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let
	us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .